Contents

Preface to the Second Edition xv

Preface to the First Edition xvii

Internet Resources within the Book xix

1 Radioactive Decay and the Origin of Gamma and X-Radiation 1

1.1 Introduction 1
1.2 Beta Decay 2
1.2.1 β^- or negatron decay 3
1.2.2 β^+ or positron decay 5
1.2.3 Electron capture (EC) 6
1.2.4 Multiple stable isotopes 7
1.3 Alpha Decay 7
1.4 Spontaneous Fission (SF) 8
1.5 Minor Decay Modes 8
1.6 Gamma Emission 8
1.6.1 The electromagnetic spectrum 9
1.6.2 Some properties of nuclear transitions 9
1.6.3 Lifetimes of nuclear energy levels 10
1.6.4 Width of nuclear energy levels 10
1.6.5 Internal conversion 11
1.6.6 Abundance, yield and emission probability 11
1.6.7 Ambiguity in assignment of nuclide identity 11
1.7 Other Sources of Photons 12
1.7.1 Annihilation radiation 12
1.7.2 Bremsstrahlung 13
1.7.3 Prompt gammas 13
1.7.4 X-rays 13
1.8 The Mathematics of Decay and Growth of Radioactivity 15
1.8.1 The decay equation 15
1.8.2 Growth of activity in reactors 16
1.8.3 Growth of activity from decay of a parent 17
1.9 The Chart of the Nuclides 19
1.9.1 A source of nuclear data 19
1.9.2 A source of generic information 20
Practical Points 22
Further Reading 23

2 Interactions of Gamma Radiation with Matter 25

2.1 Introduction 25
2.2 Mechanisms of Interaction 25
2.2.1 Photoelectric absorption 27
2.2.2 Compton scattering 28
2.2.3 Pair production 29
2.3 Total Attenuation Coefficients 29
2.4 Interactions within the Detector 30
2.4.1 The very large detector 30
2.4.2 The very small detector 31
2.4.3 The 'real' detector 32
2.4.4 Summary 32
2.5 Interactions within the Shielding 33
2.5.1 Photoelectric interactions 33
2.5.2 Compton scattering 34
2.5.3 Pair production 35
2.6 Bremsstrahlung 35
2.7 Attenuation of Gamma Radiation 36
2.8 The Design of Detector Shielding 36
Practical Points 38
Further Reading 38

3 Semiconductor Detectors for Gamma-Ray Spectrometry 39

3.1 Introduction 39
3.2 Semiconductors and Gamma-Ray Detection 40
3.2.1 The band structure of solids 40
3.2.2 Mobility of holes 40
3.2.3 Creation of charge carriers by gamma radiation 41
3.2.4 Suitable semiconductors for gamma-ray detectors 41
3.2.5 Newer semiconductor materials 42
3.3 The Nature of Semiconductors 43

4 The Manufacture of Germanium Detectors 45
3.4.1 Introduction 45
3.4.2 The manufacturing process 45
3.4.3 Lithium-drifted detectors 47
3.4.4 The detector configurations available 47
3.4.5 Absorption in detector caps and dead layers 47
3.4.6 Detectors for low-energy measurements 49
3.4.7 Well detectors 49
5 Detector Capacitance 49
3.5.1 Microphonic noise 50
6 Charge Collection in Detectors 50
3.6.1 Charge collection time 50
3.6.2 Shape of the detector pulse 51
3.6.3 Timing signals from germanium detectors 52
3.6.4 Electric field variations across the detector 52
3.6.5 Removing weak field regions from detectors 53
3.6.6 Trapping of charge carriers 53
3.6.7 Radiation damage 54
7 Packaging of Detectors 55
3.7.1 Construction of the detector mounting 55
3.7.2 Exotic detectors 57
3.7.3 Loss of coolant 58
3.7.4 Demountable detectors 58
3.7.5 Customer repairable detectors 58
3.7.6 Electrical cooling of detectors 59
actical Points 59
rther Reading 59

lectronics for Gamma-Ray Spectrometry 61
1 The General Electronic System 61
4.1.1 Introduction 61
4.1.2 Electronic noise and its implications for spectrum resolution 62
4.1.3 Pulse shapes in gamma spectrometry systems 63
4.1.4 Impedance – inputs and outputs 64
4.1.5 The impedance of cabling 64
4.1.6 Impedance matching 65
2 Detector Bias Supplies 66
3 Preamplifiers 66
4.3.1 Resistive feedback preamplifiers 67
4.3.2 Reset preamplifiers 69
4.3.3 The noise contribution of preamplifiers 69
4.3.4 The rise time of preamplifiers 70
4.4 Amplifiers and Pulse Processors 70
4.4.1 The functions of the amplifier 70
4.4.2 Pulse shaping 71
4.4.3 The optimum pulse shape 72
4.4.4 The optimum pulse shaping time constant 73
4.4.5 The gated integrator amplifier 74
4.4.6 Pole-zero cancellation 75
4.4.7 Baseline shift 76
4.4.8 Pile-up rejection 77
4.4.9 Amplifier gain and overview 78
4.5 Resolution Enhancement 80
4.5.1 New semiconductor materials 80
4.6 Multichannel Analysers and their Analogue-to-Digital Converters 81
4.6.1 Introduction 81
4.6.2 Pulse range selection 82
4.6.3 The ADC input gate 83
4.6.4 The ADC 84
4.6.5 MCA conversion time and dead time 86
4.6.6 Choosing an ADC 87
4.6.7 Linearity in MCAs 88
4.6.8 Optimum spectrum size 89
4.6.9 MCA terms and definitions 89
4.6.10 Arrangement of the MCA function 91
4.6.11 Simple MCA analysis functions 91
4.7 Live Time Correction and Loss-Free Counting 92
4.7.1 Live time clock correction 92
4.7.2 The Gedcke–Hale method 92
4.7.3 Use of a pulser 92
4.7.4 Loss-free counting (LFC) 93
4.7.5 MCA throughput 94
4.8 Spectrum Stabilization 94
4.8.1 Analogue stabilization 95
4.8.2 Digital stabilization 95
4.9 Coincidence and Anticoincidence Gating 96
4.10 Multiplexing and Multiscaling 96
4.11 Digital Pulse Processing Systems 97
Practical Points 98
Further Reading 99

5 Statistics of Counting **101**
5.1 Introduction 101
5.1.1 Statistical statements 101
5.2 Counting Distributions 102
5.2.1 The binomial distribution 102
5.2.2 The Poisson and Gaussian distributions 104
5.3 Sampling Statistics 104
5.3.1 Confidence limits 105
5.3.2 Combining the results from different measurements 107
5.3.3 Propagation of uncertainty 108
5.4 Peak Area Measurement 108
5.4.1 Simple peak integration 109
5.4.2 Peaked-background correction 111
5.5 Optimizing Counting Conditions 111
5.5.1 Optimum background width 111
5.5.2 Optimum spectrum size 112
5.5.3 Optimum counting time 113
5.6 Counting Decision Limits 114
5.6.1 Critical limit (L_C) 114
5.6.2 Upper limit (L_U) 116
5.6.3 Confidence limits 117
5.6.4 Detection limit (L_D) 117
5.6.5 Determination limit (L_Q) 118
5.6.6 Other calculation options 118
5.6.7 Minimum detectable activity (MDA) 119
5.6.8 Uncertainty of the (L_U) and MDA 120
5.6.9 An example by way of summary 120
5.7 Special Counting Situations 121
5.7.1 Non-Poisson counting 121
5.7.2 Low numbers of counts 121
5.7.3 Non-Poisson statistics due to pile-up rejection and loss-free counting 122
5.8 Uncertainty Budgets 123
5.8.1 Introduction 123
5.8.2 Accuracy and precision 124
5.8.3 Types of uncertainty 124
5.8.4 Types of distribution 124
5.8.5 Uncertainty on sample preparation 124
5.8.6 Counting uncertainties 125
5.8.7 Calibration uncertainties 126
5.8.8 An example of an uncertainty budget 126
Practical Points 128
Further Reading 128

6 Resolution: Origins and Control **131**
6.1 Introduction 131
6.2 Charge Production – ω_P 133
6.2.1 Germanium versus silicon 133
6.2.2 Germanium versus sodium iodide 134
6.2.3 Temperature dependence of resolution 134
6.3 Charge Collection – ω_C 134
6.3.1 Mathematical form of ω_C 135
6.4 Electronic Noise – ω_E 136
6.4.1 Parallel noise 136
6.4.2 Series noise 137
6.4.3 Flicker noise 137
6.4.4 Total electronic noise and shaping time 137
6.5 Resolving the Peak Width Calibration 138
Practical Points 141
Further Reading 141
References 141

7 Spectrometer Calibration **143**
7.1 Introduction 143
7.2 Reference Data for Calibration 143
7.3 Sources for Calibration 144
7.4 Energy Calibration 144
7.4.1 Errors in peak energy determination 146
7.5 Peak Width Calibration 147
7.5.1 Factors affecting peak width 147
7.5.2 Algorithms for peak width estimation 147
7.5.3 Estimation of the peak height 149
7.5.4 Anomalous peak widths 149
7.6 Efficiency Calibration 150
7.6.1 Which efficiency? 150
7.6.2 Full-energy peak efficiency 151
7.6.3 Are efficiency calibration curves necessary? 152
7.6.4 The effect of source-to-detector distance 152
7.6.5 Calibration errors due to difference in sample geometry 153
7.6.6 An empirical correction for sample height 154
7.6.7 Effect of source density on efficiency 155
7.6.8 Efficiency loss due to random summing (pile-up) 158
7.6.9 True coincidence summing 159
7.6.10 Corrections for radioactive decay 159

7.6.11 Electronic timing problems 160
7.7 Mathematical Efficiency Calibration 160
7.7.1 ISOCS 161
7.7.2 LabSOCS 162
7.7.3 Other programs 162
Practical Points 162
Further Reading 163

8 True Coincidence Summing 165
8.1 Introduction 165
8.2 The Origin of Summing 166
8.3 Summing and Solid Angle 166
8.4 Spectral Evidence of Summing 167
8.5 Validity of Close Geometry Calibrations 168
8.5.1 Efficiency calibration using QCYK mixed nuclide sources 168
8.6 Summary 171
8.7 Summing in Environmental Measurements 171
8.8 Achieving Valid Close Geometry Efficiency Calibrations 172
8.9 TCS, Geometry and Composition 174
8.10 Achieving 'Summing-free' measurements 175
8.10.1 Using the 'interpolative fit' to correct for TCS 175
8.10.2 Comparative activity measurements 175
8.10.3 Using correction factors derived from efficiency calibration curves 176
8.10.4 Correction of results using 'bodged' nuclear data 176
8.11 Mathematical Summing Corrections 176
8.12 Software for Correction of TCS 178
8.12.1 GESPECOR 179
8.12.2 Calibrations using summing nuclides 179
8.12.3 TCS correction in spectrum analysis programs 179
Practical Points 180
Further Reading 180

9 Computer Analysis of Gamma-Ray Spectra 183
9.1 Introduction 183
9.2 Methods of Locating Peaks in the Spectrum 185
9.2.1 Using regions-of-interest 185
9.2.2 Locating peaks using channel differences 185
9.2.3 Derivative peak searches 185
9.2.4 Peak searches using correlation methods 186
9.2.5 Checking the acceptability of peaks 187
9.3 Library Directed Peak Searches 187
9.4 Energy Calibration 188
9.5 Estimation of the Peak Centroid 189
9.6 Peak Width Calibration 189
9.7 Determination of the Peak Limits 191
9.7.1 Using the width calibration 192
9.7.2 Individual peak width estimation 192
9.7.3 Limits determined by a moving average minimum 192
9.8 Measurements of Peak Area 192
9.9 Full Energy Peak Efficiency Calibration 193
9.10 Multiplet Peak Resolution by Deconvolution 195
9.11 Peak Stripping as a Means of Avoiding Deconvolution 196
9.12 The Analysis of the Sample Spectrum 197
9.12.1 Peak location and measurement 198
9.12.2 Corrections to the peak area for peaked background 198
9.12.3 Upper limits and minimum detectable activity 198
9.12.4 Comparative activity estimations 199
9.12.5 Activity estimations using efficiency curves 199
9.12.6 Corrections independent of the spectrometer 199
9.13 Nuclide Identification 200
9.13.1 Simple use of look-up tables 200
9.13.2 Taking into account other peaks 200
9.14 The Final Report 200
9.15 Setting Up Nuclide and Gamma-Ray Libraries 201
9.16 Buying Spectrum Analysis Software 202
9.17 The Spectrum Analysis Programs Referred to in the Text 202
Practical Points 202
Further Reading 203

12.2.2 Transistor reset and pulsed optical reset preamplifiers 244
12.3 Thermal Cycling of the Detector 244
12.3.1 The origin of the problem 244
12.3.2 The thermal cycling procedure 245
12.3.3 Frosted detector enclosure 246
12.4 Ground Loops, Pick-up and Microphonics 246
12.4.1 Ground loops 246
12.4.2 Electromagnetic pick-up 247
12.4.3 Microphonics 249
Practical Points 250
Further Reading 250

13 Low Count Rate Systems 251
13.1 Introduction 251
13.2 Counting with High Efficiency 253
13.2.1 MDA: efficiency and resolution 253
13.2.2 MDA: efficiency, background and counting period 253
13.3 The Effect of Detector Shape 257
13.3.1 Low energy measurements 257
13.3.2 Well detectors 258
13.3.3 Sample quantity and geometry 259
13.4 Low Background Systems 262
13.4.1 The background spectrum 263
13.4.2 Low background detectors 263
13.4.3 Detector shielding 265
13.4.4 The graded shield 265
13.4.5 Airborne activity 266
13.4.6 The effect of cosmic radiation 266
13.4.7 Underground measurements 269
13.5 Active Background Reduction 270
13.5.1 Compton suppression systems 270
13.5.2 Veto guard detectors 273
13.6 Ultra-Low-Level Systems 273
Practical Points 276
Further Reading 276

14 High Count Rate Systems 279
14.1 Introduction 279
14.2 Detector Throughput 280
14.3 Preamplifiers for High Count Rate 281
14.3.1 Energy rate saturation 281
14.3.2 Energy resolution 283
14.3.3 Dead time 283
14.4 Amplifiers 283
14.4.1 Time constants and pile-up 284
14.4.2 The gated integrator 284
14.4.3 Pole zero correction 285
14.4.4 Amplifier stability – peak shift 285
14.4.5 Amplifier stability – resolution 285
14.4.6 Overload recovery 286
14.5 Digital Pulse Processing 286
14.6 The ADC and MCA 288
14.7 Dead Times and Throughput 288
14.7.1 Extendable and non-extendable dead time 289
14.7.2 Gated integrators 290
14.7.3 DSP systems 291
14.7.4 Theory versus practice 291
14.8 System Checks 292
Practical Points 293
Further Reading 293

15 Ensuring Quality in Gamma-Ray Spectrometry 295
15.1 Introduction 295
15.2 Nuclear Data 296
15.3 Radionuclide Standards 296
15.4 Maintaining Confidence in the Equipment 297
15.4.1 Setting up and maintenance procedures 297
15.4.2 Control charts 298
15.4.3 Setting up a control chart 299
15.5 Gaining Confidence in the Spectrum Analysis 301
15.5.1 Test spectra 301
15.5.2 Computer-generated test spectra 302
15.5.3 Test spectra created by counting 306
15.5.4 Assessing spectrum analysis performance 307
15.5.5 Intercomparison exercises 310
15.5.6 Assessment of intercomparison exercises 311
15.6 Maintaining Records 311
15.7 Accreditation 312

Practical Points 313
Further Reading 313
Internet Sources of Information 314

16 Gamma Spectrometry of Naturally Occurring Radioactive Materials (NORM) 315
16.1 Introduction 315
16.2 The NORM Decay Series 315
16.2.1 The uranium series – ^{238}U 316
16.2.2 The actinium series – ^{235}U 316
16.2.3 The thorium series – ^{232}Th 317
16.2.4 Radon loss 317
16.2.5 Natural disturbance of the decay series 318
16.3 Gamma Spectrometry of the NORM Nuclides 318
16.3.1 Measurement of ^{7}Be 318
16.3.2 Measurement of ^{40}K 318
16.3.3 Gamma spectrometry of the uranium/thorium series nuclides 318
16.3.4 Allowance for natural background 319
16.3.5 Resolution of the 186 keV peak 319
16.3.6 Other spectral interferences and summing 322
16.4 Nuclear Data of the NORM Nuclides 324
16.5 Measurement of Chemically Modified NORM 324
16.5.1 Measurement of separated uranium 325
16.5.2 Measurement of separated thorium 325
16.5.3 'Non-natural' thorium 326
16.5.4 Measurement of gypsum – a cautionary tale 327
16.5.5 General observations 328
Further Reading 328

17 Applications 329
17.1 Gamma Spectrometry and the CTBT 329
17.1.1 Background 329
17.1.2 The global verification regime 329
17.1.3 Nuclides released in a nuclear explosion 330
17.1.4 Measuring the radionuclides 331
17.1.5 Current status 332
17.2 Gamma Spectrometry of Nuclear Industry Wastes 333
17.2.1 Measurement of isotopically modified uranium 333
17.2.2 Measurement of transuranic nuclides 333
17.2.3 Waste drum scanning 334
17.3 Safeguards 335
17.3.1 Enrichment meters 336
17.3.2 Plutonium spectra 336
17.3.3 Fresh and aged samples 338
17.3.4 Absorption of gamma-rays 338
17.3.5 Hand-held monitors 338
17.4 PINS – Portable Isotopic Neutron Spectrometry 340
Further Reading 340

Appendix A: Sources of Information 343
A.1 Introduction 343
A.2 Nuclear Data 343
A.2.1 Recent developments in the distribution of nuclear data 344
A.2.2 On line internet sources of gamma-ray emission data 345
A.2.3 Off-line sources of gamma-ray emission data 346
A.2.4 Nuclear data in print 346
A.3 Internet Sources of Other Nuclear Data 347
A.4 Chemical Information 347
A.5 Miscellaneous Information 348
A.6 Other Publications in print 348

Appendix B: Gamma- and X-Ray Standards for Detector Calibration 351

Appendix C: X-Rays Routinely Found in Gamma Spectra 359

Appendix D: Gamma-Ray Energies in the Detector Background and the Environment 361

Appendix E: Chemical Names, Symbols and Relative Atomic Masses of the Elements 365

***Glossary* 369**

***Index* 381**