

Contents

1	Applications and Developments of Thin Film Technology . . .	1
	<i>by H. Frey</i>	
2	Relevance of the Vacuum Technology for Thin Film Coatings	5
	<i>by H. Frey</i>	
2.1	Introduction	5
2.2	Influence of Residual Gas on Film Quality	5
2.3	Generation of Vacuum	7
2.4	Vacuum Measurement	10
2.4.1	Thermal Conductivity Gauge	10
2.4.2	Friction Vacuum Gauge	11
2.4.3	Cold Cathode Ionization Vacuum Gauge	11
2.4.4	Hot-Cathode Ionization Gauge	11
2.4.5	Total Pressure Measurement in Coating Processes	11
2.4.6	Partial Pressure Measurement	12
3	Vacuum Evaporation	13
	<i>by H. Frey</i>	
3.1	Introduction	13
3.2	Fundamentals	13
3.2.1	Evaporation Processes	13
3.2.2	Transport Phase	15
3.2.3	Condensation Phase	16
3.3	Evaporation of Different Materials	17
3.3.1	Chemical Elements	17
3.3.2	Alloys	18
3.3.3	Compounds	26
3.4	Vapour Distribution	29
3.4.1	Small Surface Evaporators	29
3.4.2	Evaporation Arrangements with Expanded Source Distribution	33
3.4.3	Vapour Propagation with Small Free Path Length	34
3.5	Equipment Technology	37
3.5.1	Prefaces	37
3.5.2	Auxiliary Equipment for Evaporation Plants . . .	38
3.5.3	Electron Emission	44
3.5.4	Evaporation Rate	53

3.6	Ion Plating	62
3.6.1	Characterization of Ion Plating	62
3.6.2	Influence on the Film Characteristics and Consequences for the Coating Process	64
3.6.3	Equipment for Ion Plating	64
3.6.4	Structural Constitution of the Ion Plated Films	66
3.6.5	Adhesive Strength of Ion Plated Films	68
3.6.6	Reactive Ion Plating	68
4	Basic Principle of Plasma Physics	73
	<i>by H. Frey</i>	
4.1	Introduction	73
4.2	Quasi-Neutrality	73
4.3	Characteristic Quantities	75
4.3.1	Langmuir Plasma Frequency	75
4.3.2	Debye Shielding Length	75
4.3.3	Landau Length and Plasma Parameters	76
4.4	Motion of Charged Particles in Electromagnetic Fields	77
4.4.1	Maxwell Equations	77
4.4.2	Equation of Motion and Law of Conservation of Energy	78
4.4.3	Larmor Motion	79
4.5	Collision Determined Plasmas	80
4.5.1	Distribution of Velocity	80
4.5.2	Mean Free Path and Collision Frequencies	82
4.5.3	Drift Motion of Charge Carriers in an Electrical Field with Consideration of Collisions	83
4.5.4	Ionization and Recombination	85
4.5.5	Plasma as Continuum	91
4.5.6	Transportation Processes	102
4.6	Discharge Modes	105
4.6.1	Direct Current Discharges	105
4.6.2	High Frequency Discharges	111
5	Gaseous Phase and Surface Processes	117
	<i>by H. Frey</i>	
5.1	Elementary Gaseous Phase and Surface Reactions	117
5.1.1	Equilibrium Constant	118
5.2	Gaseous Phase Kinetics	118
5.2.1	Consecutive Reactions of First Order	119
5.2.2	Reactions Moving in Opposite Directions	121
5.2.3	Three-Body Accretion Collisions	123
5.2.4	Three-Body Positive–Negative Ion Recombination	124
5.3	Surface Processes	124
5.3.1	Neutralization of Positive Ions and Emission of Secondary Electrons	124

	5.3.2	Adsorption and Desorption	128
	5.3.3	Fragmentation	131
6		Cathode Sputtering	133
		<i>by H. Frey</i>	
	6.1	Introduction	133
	6.2	Sputtering	133
	6.2.1	Angle Distribution of Sputtered Particles	138
	6.2.2	Sputtering Effects with Single-Crystal Solids	139
	6.3	Coating with Sputtering	143
	6.4	DC Diode Sputtering	143
	6.5	Triode Sputtering	145
	6.6	RF (Radio Frequency) Sputtering	146
	6.7	Bias Sputtering	150
	6.8	Reactive Sputtering	150
	6.9	Magnetron Discharges	152
	6.9.1	Structure	152
	6.9.2	Function of the Magnetron	152
	6.9.3	Estimation of Plasma Density	155
	6.9.4	Discharge Power	156
	6.9.5	Types	156
	6.9.6	Cathodes	157
	6.9.7	Shutters	161
	6.9.8	Infrared Heating	162
	6.9.9	Rate and Film Thickness Measuring Instruments	162
	6.9.10	Two-Chamber Equipment	163
	6.9.11	Multi-Chamber Equipments	164
7		Plasma Treatment Methods	167
		<i>by H. Frey</i>	
	7.1	Plasma Polymerization	167
	7.1.1	Introduction	167
	7.1.2	Physics and Chemistry of Plasma Polymerization	168
	7.2	Plasma Diffusion Treatment	171
	7.2.1	Description of the Method	171
	7.2.2	Fundamental Processes	172
	7.2.3	Correlations Between Different Plasma Parameters	173
	7.2.4	Plasma Nitration of Titanium	174
	7.2.5	Plasma Nitration of Aluminium	174
	7.3	Plasma Spraying	175
	7.3.1	Process Variants	176
8		Particle Beam Sources	181
		<i>by H. Frey</i>	
	8.1	Introduction	181
	8.2	Basic Processes of Ion–Solid Interaction	182
	8.2.1	Loss of Energy	182

8.2.2	Range Distances	185
8.2.3	Collision Cascades and Radiation Damage	186
8.2.4	Ion Mixing	187
8.2.5	Irradiation Amplified Diffusion	187
8.2.6	Surface Texture and Growth Mode	188
8.2.7	Density and Stress	190
8.2.8	Phases in Material Films	191
8.3	Particle Beam Sources	192
8.3.1	Ion Beam Generation	192
8.3.2	Large Area Sources	198
8.4	Application Areas of Ion Beams	204
8.4.1	Primary Ion Beam Deposition (PIBD)	205
8.4.2	Secondary Ion Beam Deposition (SIBD)	206
8.4.3	Ion Beam Etching (IBE, Reactive RIBE)	206
8.5	Ion Implantation	206
8.5.1	Introduction to Implantation	206
8.5.2	Devices for Ion Implantation	217
8.5.3	Pulse Implantation	219
8.5.4	Ion Beam-Assisted Deposition	221
9	Chemical Vapor Deposition (CVD)	225
	<i>by H. Frey</i>	
9.1	Introduction	225
9.2	Physicochemical Bases	226
9.2.1	Initiator Molecules	229
9.2.2	Transportation Phase	234
9.2.3	Deposition and Layer Generation	239
9.3	Equipment for CVD Processes	244
9.3.1	Batch Reactors with Operating Points Within the Kinetically Controlled Range	244
9.3.2	Reactors Operating Within the Mass-Transport Controlled Range	245
9.4	Plasma-Enhanced Chemical Deposition from the Gaseous Phase (PECVD)	246
9.4.1	Deposition of Amorphous Silicon (a-Si:H)	247
9.5	Photoinitiated Vapor Deposition	250
9.5.1	Advantageous Features of PICVD	251
10	Physical Basics of Modern Methods of Surface and Thin Film Analysis	253
	<i>by H. Frey</i>	
10.1	Introduction	253
10.2	Ion Spectroscopes	254
10.2.1	Ion Backscattering	254
10.2.2	Secondary Ion Mass Spectrometry (SIMS)	258
10.2.3	Neutral Particle Spectrometry	262
10.2.4	IPP (Ion-Induced Photo Production)	263
10.2.5	PIXE (Particle-Induced X-Ray Emission)	264

10.3	Electron-Spectroscopic Methods: Auger Electron Spectroscopy (AES) and X-Ray Photoelectron Spectroscopy (XPS)	265
10.3.1	Auger Electron Spectroscopy (AES)	267
10.3.2	ESCA (Electron Spectroscopy for Chemical Analysis), X-Ray Photo Electron Spectroscopy (XPS)	268
10.3.3	UPS (Ultraviolet Photoelectron Spectroscopy)	270
10.4	Inverse Photoemission	271
10.5	Electron Energy Loss Spectroscopy	273
10.6	Diffraction of Slow and Fast Electrons	273
10.7	Image Methods	274
11	Insitu Measurements	279
	<i>by H. Frey</i>	
11.1	Determination of Film Thickness by Resistance Measurement	279
11.2	Rate Measurement by Particle Ionization and Excitation	280
11.2.1	Introduction	280
11.3	Film Thickness and Rate of Deposition Measurements with Quartz Crystal Oscillators	283
11.3.1	Introduction	283
11.4	Optical Measuring Procedures	287
11.4.1	Introduction	287
11.4.2	Systematics of Optical Measuring of Film Thickness	287
11.4.3	Calculation of Optical Film Systems	290
11.5	Determination of the Film Thickness by X-Ray Emission and X-Ray Fluorescence	294
11.6	Atomic Emission Spectroscopy	296
12	Measurements of Thin Layers After the Coating Process	301
	<i>by H. Frey and T. Helmut</i>	
12.1	Measurements of Thermal Conductivity	301
12.1.1	Introduction	301
12.1.2	Experimental Determination	301
12.2	Electrical Conductivity	301
12.2.1	Definition	301
12.2.2	Methods of Determination	301
12.3	Magnetic Properties	302
12.3.1	Properties of Magnetic Layers	302
12.3.2	Magnetic Anisotropy	303
12.3.3	Characteristics of Magnetization Reversal	304
12.3.4	Magnetic Measuring Methods (Overview)	305
12.3.5	Inductive Methods	305
12.3.6	Mechanical Measuring Methods	306
12.3.7	Optical Measuring Methods	306
12.4	Measurement of Color Characteristics	308

12.4.1	Introduction	308
12.4.2	Colorimetry	310
12.4.3	Color Measuring Instruments	312
12.5	Optical Properties of Thin Films	312
12.5.1	Reflectivity and Transmission	312
12.5.2	Ellipsometry	314
12.5.3	Scattering	319
12.5.4	Color	320
12.6	Spectrometers	321
12.6.1	Grating Monochromators and Spectrometers	321
12.6.2	Fourier Transform Spectrometers	323
12.7	Microscopy	324
12.7.1	Optical Microscopes	324
12.7.2	Electron Microscopy	329
12.8	Permeation	337
12.8.1	Measurement Principles	338
12.9	Mechanical Stresses in Thin Films	339
12.9.1	Introduction	339
12.9.2	Interference Optical Measurement	340
12.9.3	Electrical Measurements	341
12.9.4	Laser Scanning Method	341
12.10	Hardness Measurements	341
12.10.1	Introduction	341
12.10.2	Influence of Measurement Conditions on the Hardness Values	342
12.10.3	Measuring Sets and Their Application	343
12.11	Adhesion	344
12.11.1	Introduction	344
12.11.2	Measuring Instruments and Measuring Methods	345
12.12	Roughness of Solid Surfaces	349
12.12.1	Introduction	349
12.12.2	Definitions	349
12.12.3	Measuring Instruments and Measuring Methods	350
12.13	Measuring of Film Thickness	351
12.13.1	Film Thickness Determination by Particle Emission	351
12.14	Determination of Pinhole Densities	353
13	Nanoparticle Films	357
	<i>by H. R. Khan</i>	
13.1	Introduction to Nanomaterials	357
13.2	Synthesis of Nanoparticle Films	358
13.2.1	Diamond Films Deposited by Chemical Vapor Deposition (CVD) and Pulsed Laser Ablation (PLD) Techniques	358
13.2.2	Magnetic Nanocomposites	359
13.2.3	Disordered Magnetic Nanocomposites ($\text{Co}_{50}\text{Fe}_{50}$) _x (Al_2O_3) _{100-x}	360

13.2.4	Nanostructured Nanocomposites Films of Co and CoFe	366
13.2.5	Nanoparticle Transparent and Electrically Conducting Zinc Oxide Films	368
	Index	375