

Contents

1	Lines on the Drawing.....	11
1.1	The usage of the lines in the drawings.....	12
1.1.1	Examples of different lines in a technical drawing.....	13
2	Drawing to Scale.....	14
2.1	Standardised scales.....	14
2.1.1	Linearity of the standardised scales.....	15
2.1.2	Choice of the appropriate scale.....	15
2.1.3	Usage of more drawing scales.....	16
2.2	Scale in the corner title.....	16
3	Lettering of the Drawings.....	18
3.1	Number of squares number for type A and B.....	20
3.2	Direction of lettering.....	21
4	Standard Sheets, Sizes of Drawings.....	22
4.1	Where the sheet lengths ratio $1:\sqrt{2}$ comes from.....	23
4.1.1	Accounting the length side of the A0 sheet.....	24
4.2	Frames drawn around the drawing.....	24
4.2.1	Orientation fields.....	25
4.3	All components of the technical drawing.....	25
4.4	Drawing sheets sizes.....	26
4.5	Position of standard sheets.....	27
4.6	Drawing folding.....	27
4.6.1	Folding types.....	28
	Basic folding.....	28
	Folding for direct binding of drawing.....	29
	Folding for binding of drawing with an auxiliary strip.....	29
4.6.2	Special sheets.....	30
5	Material Specification.....	31
6	Projection Methods.....	33
6.1	Pictorial drawings.....	33

6.1.1	Axonometric projection	33
6.1.2	Oblique projection	34
6.1.3	Perspective projection	34
6.1.4	Orthographic projection	35
	How to construct the principal views?	35
	How to project	36
	How to transform the 3D real object into the 2D drawing	37
	Six principal views	39
	Projection method 1 and projection method 3	40
7	Recommended Progress for Free Hand Sketching	42
8	Real Object Drawing	45
8.1	Auxiliary projection plane	46
8.2	Representation of rotary details	46
8.3	Representation of completely flat details	49
8.4	Simplification of drawings views	50
8.4.1	Repeated elements	50
8.4.2	Interrupted views	52
8.4.3	Intersections	53
	Intersection of rotary bodies	54
	Small bevels, clamp	55
9	Sections – Cuts	56
9.1	Hatching	57
9.1.1	Hatching in assembly drawing	57
9.1.2	Hatching of very thin details	58
9.2	Specification of the cutting plane and corresponding section	58
9.3	Half section	59
9.4	Break of cutting plane	60
9.5	Offset section	61
9.6	Perpendicular section and longitudinal section	62
9.7	Non-sectioned details	63
9.8	Local section	64
9.9	Ribs and webs	64
9.10	Cross section	65
9.11	Section examples	66
10	Dimensioning	70
10.1	Basic rules for dimensioning	71

10.1.1	Dimension line.....	71
10.1.2	Extension lines.....	72
10.1.3	Arrowheads.....	73
10.1.4	Dimension figure.....	73
	Direction of dimension figure lettering.....	74
10.1.5	Auxiliary lines.....	75
10.1.6	Dimensioning of circular holes, arcs, angles, thicknesses.....	75
10.1.7	Dimensioning of half section.....	76
10.1.8	Leaders.....	76
10.2	Dimension systems.....	77
10.2.1	Chain dimensioning.....	77
10.2.2	Dimensioning from the datum.....	79
10.2.3	Combined dimensioning.....	80
10.3	The main principles of dimensioning.....	80
10.3.1	Rightness.....	80
10.3.2	Clearness.....	81
10.3.3	Completeness.....	81
10.3.4	Clear arrangement.....	82
10.3.5	Purposefulness.....	82
10.4	Dimensioning of some specific elements.....	83
10.4.1	Dimensioning of radii.....	83
10.4.2	Dimensioning the length of an arc.....	83
10.4.3	Dimensioning of a bevel.....	84
10.4.4	Dimensioning of a cone.....	85
10.4.5	Dimensioning of chamfering.....	86
10.4.6	Dimensioning of a work centre.....	87
10.4.7	Dimensioning of a countersink.....	88
10.4.8	Dimensioning of a pyramid.....	89
10.4.9	Dimensioning of a drilled hole.....	89
10.4.10	Dimensioning of hole positions.....	91
	Dimensioning of hole positions by a table (by coordinates).....	92
	Dimensioning by a table.....	92
10.4.11	Dimensioning of symmetrical parts.....	93
10.4.12	Dimensioning of an irregular curve contour.....	93
	Rotary irregular curve shape.....	94
11	Tolerancing and Fitting.....	95
11.1	Deviations of dimension, shape and position.....	95

11.1.1	Deviations of dimension.....	96
11.1.2	Deviations of shape.....	96
11.1.3	Deviations of position.....	96
11.2	Fitting terminology.....	97
11.3	Fit types.....	98
11.3.1	Clearance fit.....	99
11.3.2	Interference fit.....	99
11.3.3	Transition fit.....	100
11.4	Fit symbol.....	100
11.4.1	Positions of tolerance zones.....	101
11.4.2	Degree of precision.....	102
	What degree of precision we will use for our drawings?.....	103
11.5	Systems of fits.....	103
11.5.1	Hole Basic System.....	103
11.5.2	Shaft Basic System.....	104
11.6	Fitting tables.....	105
11.6.1	Fitting Table of Hole Basic System.....	105
11.6.2	Fitting Table of Shaft Basic System.....	107
11.7	Inscription of tolerances and fits.....	107
11.7.1	Tolerances and fits of rotary details.....	108
11.7.2	Tolerances of length precision.....	108
11.7.3	Prescribing of angle precision.....	109
11.7.4	Tables of non-tolerated dimensions.....	110
	Table of limit deviations for length dimensions.....	110
	Table of limit deviations for chamfering and filling dimensions.....	110
	Table of limit deviations for angles.....	111
11.8	Deviations of the shape.....	111
11.8.1	Deviations of a shape (example).....	112
11.8.2	Prescribing the deviations of shape in the drawing.....	112
11.8.3	Prescribing the deviations of shape (example).....	114
11.9	Deviations of position.....	115
11.9.1	Deviations of position (examples).....	116
11.9.2	Prescribing deviations of position in the drawing.....	117
11.9.3	Other frequently used basic deviations of position.....	118
11.9.4	Prescribing deviations of position (example).....	119
12	Surface Quality Parameters.....	120
12.1	Surface roughness.....	120

12.1.1	Basic roughness terminology.....	121
12.1.2	Basic characteristics of surface roughness.....	122
	Amplitude characteristics	122
	Frequency characteristics of roughness	124
	Geometric characteristics of roughness	124
12.1.3	Denotating and prescribing of roughness	125
	Basic roughness symbol.....	125
	Complex roughness symbol.....	125
	Roughness direction.....	126
	Roughness values.....	126
	Rotating the roughness symbol.....	127
	Special cases of prescribing roughness.....	127
12.1.4	Surface roughness achieved by different ways of machining.....	129
12.2	Prescribing extra surface treatments.....	129
13	Drafting and Dimensioning of Threads, Screws and Nuts	131
13.1	Thread terminology.....	132
13.2	Most used types of threads.....	134
13.2.1	Metric thread.....	134
13.2.2	Whitworth thread.....	135
13.2.3	Pipe thread	135
13.2.4	Edison thread	136
13.2.5	Armour thread.....	137
13.2.6	Trapezoidal thread	137
13.2.7	Buttress thread	138
13.2.8	Round thread.....	139
13.2.9	Thread for protective glass of lamps.....	139
13.3	Drafting threads	140
13.3.1	Chamfered edge of the thread.....	140
13.3.2	End of thread and run-out	140
13.3.3	Threads in the section view	142
13.3.4	Threads in the assembly drawing.....	142
13.3.5	Drafting of hexagonal heads of screws.....	143
13.4	Dimensioning of the threads	144
13.4.1	External thread dimensioning.....	144
13.4.2	Internal thread dimensioning.....	145
13.4.3	Non-standard thread dimensioning.....	145
13.5	Bolted connection on the assembly drawing	145

13.5.1	Slotted head drawing	148
13.6	Special screw and nut types	148
14	Drawing and Dimensioning of Electrical Parts	149
14.1	Printed circuit board (PCB)	151
14.1.1	PCB advantages and disadvantages	152
14.1.2	PCB construction	153
14.1.3	Surface mounted technology	153
14.1.4	Main kinds of PCB	153
14.1.5	PCB classes	154
	Basic net	154
14.1.6	Complete documentation for manufacturing of PBC	155
	Sample and drawing of conductor pattern	156
	Sample and drawing of standard holes	156
	Drawing of special holes	157
	Sample of non-soldered mask	157
	Sample of printing	157
	Component location drawing of PCB	158
	Circuit diagram	158
	List of electronic components	158
	List of mechanical components	158
14.2	Electronic component symbols	159
14.2.1	Parts of electronic component symbol	159
14.2.2	Graphical symbols for diagrams	159
14.2.3	Rules of electronic component drawing	166
	Representation of electronic components	166
	Multi pole and single pole diagrams	167
	Labelling of electrical and electronic components	168
	Unit abbreviations and component value writing	169
14.3	Electro-technical diagrams	169
14.3.1	Power diagram	170
14.3.2	Diagrams of electrical connection	172
14.3.3	Circuit diagrams	173
14.3.4	Realisation diagrams	175
14.3.5	Kinematics diagram	177
15	Drawing and Dimensioning of Selected Electromechanical Parts	178
15.1	Gear wheels	178
15.1.1	Basic types of gear wheels	178

15.1.2	Basic parameters of the evolvent gear wheels.....	182
15.1.3	Drawing gear wheels	183
15.1.4	Dimensioning gear wheels.....	183
15.2	Springs	184
15.2.1	Dimensioning springs	185
15.2.2	The table of spring parameters.....	186
15.3	Rolling-contact bearings.....	187
15.3.1	Drafting the rolling-contact bearings.....	187
15.4	Permanent joints	189
15.4.1	Riveted joints.....	189
15.4.2	Soldered and stuck (glued) joints.....	189
15.5	Welded joints.....	190
15.5.1	Welding symbols	190
	Flash (butt) welds.....	190
	Fillet welds.....	191
16	Drawing Graphs.....	193
English - Czech Dictionary.....		196
Electronic component symbols.....		199
Six principal view names.....		201
References		202