

Contents

INFORMAČNÍ STŘEDISKO Přírodovědecké fakulty UNIVERZITY PALACKÉHO V OLOMOUCI	
Přír. č.	31340/19612
Sign.	G2/630
Knihovna kated	GPYFGE

49/666

68251-

Preface	vii
1 Radioactive Decay and the Origin of Gamma- and X-Radiation	1
2 Interactions of Gamma-Radiation with Matter	22
3 Semiconductor Detectors for Gamma-Ray Spectrometry	38
4 Electronics for Gamma-Ray Spectrometry	62
5 Statistics of Counting	104
6 Spectrometer Calibration	128
7 True Coincidence Summing	148
8 Computer Analysis of Gamma-Ray Spectra	160
9 Scintillation Spectrometry	183
10 Choosing, Setting up and Checking the Specification of a Detector	199
11 Resolution: Origins and Control	216
12 Troubleshooting	225
13 Low Count Rate Systems	237
14 High Count Rate Systems	259
15 Ensuring Quality in Gamma-Ray Spectrometry	272
Appendix A Sources of Information	291
Appendix B Gamma-Ray and X-Ray Standards for Detector Calibration	294
Appendix C Gamma-Ray Energies in the Detector Background and the Environment, Including those seen Following the Chernobyl Reactor Accident	300
Appendix D Chemical Names and Symbols	304
Appendix E Manufacturers and Suppliers Mentioned in the Text	307
Index	309