

Contents

Preface *xvii*

List of Abbreviations and Symbols *xix*

About the Authors *xxiii*

1	Introduction	1
2	Principles of X-ray Spectrometry	7
2.1	Analytical Performance	7
2.2	X-ray Radiation and Their Interaction	11
2.2.1	Parts of an X-ray Spectrum	11
2.2.2	Intensity of the Characteristic Radiation	13
2.2.3	Nomenclature of X-ray Lines	15
2.2.4	Interaction of X-rays with Matter	15
2.2.4.1	Absorption	16
2.2.4.2	Scattering	17
2.2.5	Detection of X-ray Spectra	20
2.3	The Development of X-ray Spectrometry	21
2.4	Carrying Out an Analysis	26
2.4.1	Analysis Method	26
2.4.2	Sequence of an Analysis	27
2.4.2.1	Quality of the Sample Material	27
2.4.2.2	Sample Preparation	27
2.4.2.3	Analysis Task	28
2.4.2.4	Measurement and Evaluation of the Measurement Data	28
2.4.2.5	Creation of an Analysis Report	29
3	Sample Preparation	31
3.1	Objectives of Sample Preparation	31
3.2	Preparation Techniques	32
3.2.1	Preparation Techniques for Solid Samples	32
3.2.2	Information Depth and Analyzed Volume	32
3.2.3	Infinite Thickness	36
3.2.4	Contaminations	37
3.2.5	Homogeneity	38

3.3	Preparation of Compact and Homogeneous Materials	39
3.3.1	Metals	39
3.3.2	Glasses	40
3.4	Small Parts Materials	41
3.4.1	Grinding of Small Parts Material	42
3.4.2	Preparation by Pouring Loose Powder into a Sample Cup	43
3.4.3	Preparation of the Measurement Sample by Pressing into a Pellet	44
3.4.4	Preparation of the Sample by Fusion Beads	48
3.4.4.1	Improving the Quality of the Analysis	48
3.4.4.2	Steps for the Production of Fusion Beads	49
3.4.4.3	Loss of Ignition	53
3.4.4.4	Quality Criteria for Fusion Beads	53
3.4.4.5	Preparation of Special Materials	54
3.5	Liquid Samples	55
3.5.1	Direct Measurement of Liquids	55
3.5.2	Special Processing Procedures for Liquid Samples	58
3.6	Biological Materials	58
3.7	Small Particles, Dust, and Aerosols	59
4	XRF Instrument Types	61
4.1	General Design of an X-ray Spectrometer	61
4.2	Comparison of Wavelength- and Energy-Dispersive X-Ray Spectrometers	63
4.2.1	Data Acquisition	63
4.2.2	Resolution	64
4.2.2.1	Comparison of Wavelength- and Energy-Dispersive Spectrometry	64
4.2.2.2	Resolution of WDS Instruments	66
4.2.2.3	Resolution of EDS Instruments	68
4.2.3	Detection Efficiency	70
4.2.4	Count Rate Capability	71
4.2.4.1	Optimum Throughput in ED Spectrometers	71
4.2.4.2	Saturation Effects in WDSs	72
4.2.4.3	Optimal Sensitivity of ED Spectrometers	73
4.2.4.4	Effect of the Pulse Throughput on the Measuring Time	74
4.2.5	Radiation Flux	75
4.2.6	Spectra Artifacts	76
4.2.6.1	Escape Peaks	76
4.2.6.2	Pile-Up Peak	77
4.2.6.3	Diffraction Peaks	77
4.2.6.4	Shelf and Tail	79
4.2.7	Mechanical Design and Operating Costs	79
4.2.8	Setting Parameters	80
4.3	Type of Instruments	80
4.3.1	ED Instruments	81
4.3.1.1	Handheld Instruments	82
4.3.1.2	Portable Instruments	83

4.3.1.3	Tabletop Instruments	84
4.3.2	Wavelength-Dispersive Instruments	85
4.3.2.1	Sequential Spectrometers	85
4.3.2.2	Multichannel Spectrometers	87
4.3.3	Special Type X-Ray Spectrometers	87
4.3.3.1	Total Reflection Instruments	88
4.3.3.2	Excitation by Monoenergetic Radiation	90
4.3.3.3	Excitation with Polarized Radiation	91
4.3.3.4	Instruments for Position-Sensitive Analysis	93
4.3.3.5	Macro X-Ray Fluorescence Spectrometer	94
4.3.3.6	Micro X-Ray Fluorescence with Confocal Geometry	95
4.3.3.7	High-Resolution X-Ray Spectrometers	96
4.3.3.8	Angle Resolved Spectroscopy – Grazing Incidence and Grazing Exit	96
4.4	Commercially Available Instrument Types	98
5	Measurement and Evaluation of X-ray Spectra	99
5.1	Information Content of the Spectra	99
5.2	Procedural Steps to Execute a Measurement	101
5.3	Selecting the Measurement Conditions	102
5.3.1	Optimization Criteria for the Measurement	102
5.3.2	Tube Parameters	103
5.3.2.1	Target Material	103
5.3.2.2	Excitation Conditions	104
5.3.2.3	Influencing the Energy Distribution of the Primary Spectrum	105
5.3.3	Measurement Medium	107
5.3.4	Measurement Time	108
5.3.4.1	Measurement Time and Statistical Error	108
5.3.4.2	Measurement Strategies	108
5.3.4.3	Real and Live Time	109
5.3.5	X-ray Lines	110
5.4	Determination of Peak Intensity	112
5.4.1	Intensity Data	112
5.4.2	Treatment of Peak Overlaps	112
5.4.3	Spectral Background	114
5.5	Quantification Models	117
5.5.1	General Remarks	117
5.5.2	Conventional Calibration Models	118
5.5.3	Fundamental Parameter Models	121
5.5.4	Monte Carlo Quantifications	124
5.5.5	Highly Precise Quantification by Reconstitution	124
5.5.6	Evaluation of an Analytical Method	126
5.5.6.1	Degree of Determination	126
5.5.6.2	Working Range, Limits of Detection (LOD) and of Quantification	127
5.5.6.3	Figure of Merit	129
5.5.7	Comparison of the Various Quantification Models	129

5.5.8	Available Reference Materials	131
5.5.9	Obtainable Accuracies	132
5.6	Characterization of Layered Materials	133
5.6.1	General Form of the Calibration Curve	133
5.6.2	Basic Conditions for Layer Analysis	135
5.6.3	Quantification Models for the Analysis of Layers	138
5.7	Chemometric Methods for Material Characterization	140
5.7.1	Spectra Matching and Material Identification	141
5.7.2	Phase Analysis	141
5.7.3	Regression Methods	143
5.8	Creation of an Application	143
5.8.1	Analysis of Unknown Sample Qualities	143
5.8.2	Repeated Analyses on Known Samples	144
6	Analytical Errors	149
6.1	General Considerations	149
6.1.1	Precision of a Measurement	151
6.1.2	Long-Term Stability of the Measurements	153
6.1.3	Precision and Process Capability	154
6.1.4	Trueness of the Result	156
6.2	Types of Errors	156
6.2.1	Randomly Distributed Errors	157
6.2.2	Systematic Errors	158
6.3	Accounting for Systematic Errors	159
6.3.1	The Concept of Measurement Uncertainties	159
6.3.2	Error Propagation	160
6.3.3	Determination of Measurement Uncertainties	161
6.3.3.1	Bottom-Up Method	161
6.3.3.2	Top-Down Method	162
6.4	Recording of Error Information	164
7	Other Element Analytical Methods	167
7.1	Overview	167
7.2	Atomic Absorption Spectrometry (AAS)	168
7.3	Optical Emission Spectrometry	169
7.3.1	Excitation with a Spark Discharge (OES)	169
7.3.2	Excitation in an Inductively Coupled Plasma (ICP-OES)	170
7.3.3	Laser-Induced Breakdown Spectroscopy (LIBS)	171
7.4	Mass Spectrometry (MS)	172
7.5	X-Ray Spectrometry by Particle Excitation (SEM-EDS, PIXE)	173
7.6	Comparison of Methods	175
8	Radiation Protection	177
8.1	Basic Principles	177
8.2	Effects of Ionizing Radiation on Human Tissue	178
8.3	Natural Radiation Exposure	179

- 8.4 Radiation Protection Regulations 181
- 8.4.1 Legal Regulations 181

- 9 Analysis of Homogeneous Solid Samples 183**
- 9.1 Iron Alloys 183
- 9.1.1 Analytical Problem and Sample Preparation 183
- 9.1.2 Analysis of Pig and Cast Iron 184
- 9.1.3 Analysis of Low-Alloy Steel 185
- 9.1.4 Analysis of High-Alloy Steel 187
- 9.2 Ni-Fe-Co Alloys 188
- 9.3 Copper Alloys 189
- 9.3.1 Analytical Task 189
- 9.3.2 Analysis of Compact Samples 189
- 9.3.3 Analysis of Dissolved Samples 189
- 9.4 Aluminum Alloys 191
- 9.5 Special Metals 192
- 9.5.1 Refractories 192
- 9.5.1.1 Analytical Problem 192
- 9.5.1.2 Sample Preparation of Hard Metals 192
- 9.5.1.3 Analysis of Hard Metals 193
- 9.5.2 Titanium Alloys 194
- 9.5.3 Solder Alloys 194
- 9.6 Precious Metals 195
- 9.6.1 Analysis of Precious Metal Jewelry 195
- 9.6.1.1 Analytical Task 195
- 9.6.1.2 Sample Shape and Preparation 196
- 9.6.1.3 Analytical Equipment 197
- 9.6.1.4 Accuracy of the Analysis 198
- 9.6.2 Analysis of Pure Elements 198
- 9.7 Glass Material 199
- 9.7.1 Analytical Task 199
- 9.7.2 Sample Preparation 200
- 9.7.3 Measurement Equipment 202
- 9.7.4 Achievable Accuracies 202
- 9.8 Polymers 203
- 9.8.1 Analytical Task 203
- 9.8.2 Sample Preparation 204
- 9.8.3 Instruments 205
- 9.8.4 Quantification Procedures 205
- 9.8.4.1 Standard-Based Methods 205
- 9.8.4.2 Chemometric Methods 206
- 9.9 Abrasion Analysis 209

- 10 Analysis of Powder Samples 213**
- 10.1 Geological Samples 213

- 10.1.1 Analytical Task 213
- 10.1.2 Sample Preparation 214
- 10.1.3 Measurement Technique 215
- 10.1.4 Detection Limits and Trueness 215
- 10.2 Ores 216
 - 10.2.1 Analytical Task 216
 - 10.2.2 Iron Ores 216
 - 10.2.3 Mn, Co, Ni, Cu, Zn, and Pb Ores 217
 - 10.2.4 Bauxite and Alumina 218
 - 10.2.5 Ores of Precious Metals and Rare Earths 219
- 10.3 Soils and Sewage Sludges 221
 - 10.3.1 Analytical Task 221
 - 10.3.2 Sample Preparation 221
 - 10.3.3 Measurement Technology and Analytical Performance 222
- 10.4 Quartz Sand 223
- 10.5 Cement 223
 - 10.5.1 Analytical Task 223
 - 10.5.2 Sample Preparation 224
 - 10.5.3 Measurement Technology 225
 - 10.5.4 Analytical Performance 226
 - 10.5.5 Determination of Free Lime in Clinker 227
- 10.6 Coal and Coke 227
 - 10.6.1 Analytical Task 227
 - 10.6.2 Sample Preparation 228
 - 10.6.3 Measurement Technology and Analytical Performance 229
- 10.7 Ferroalloys 230
 - 10.7.1 Analytical Task 230
 - 10.7.2 Sample Preparation 230
 - 10.7.3 Analysis Technology 232
 - 10.7.4 Analytical Performance 234
- 10.8 Slags 235
 - 10.8.1 Analytical Task 235
 - 10.8.2 Sample Preparation 235
 - 10.8.3 Measurement Technology and Analytical Accuracy 236
- 10.9 Ceramics and Refractory Materials 237
 - 10.9.1 Analytical Task 237
 - 10.9.2 Sample Preparation 237
 - 10.9.3 Measurement Technology and Analytical Performance 238
- 10.10 Dusts 239
 - 10.10.1 Analytical Problem and Dust Collection 239
 - 10.10.2 Measurement 242
- 10.11 Food 242
 - 10.11.1 Analytical Task 242
 - 10.11.2 Monitoring of Animal Feed 243
 - 10.11.3 Control of Infant Food 244
- 10.12 Pharmaceuticals 245
 - 10.12.1 Analytical Task 245

- 10.12.2 Sample Preparation and Analysis Method 245
- 10.13 Secondary Fuels 246
 - 10.13.1 Analytical Task 246
 - 10.13.2 Sample Preparation 247
 - 10.13.2.1 Solid Secondary Raw Materials 247
 - 10.13.2.2 Liquid Secondary Raw Materials 249
 - 10.13.3 Instrumentation and Measurement Conditions 250
 - 10.13.4 Measurement Uncertainties in the Analysis of Solid Secondary Raw Materials 251
 - 10.13.5 Measurement Uncertainties for the Analysis of Liquid Secondary Raw Materials 252
- 11 Analysis of Liquids 253**
 - 11.1 Multielement Analysis of Liquids 254
 - 11.1.1 Analytical Task 254
 - 11.1.2 Sample Preparation 254
 - 11.1.3 Measurement Technology 254
 - 11.1.4 Quantification 255
 - 11.2 Fuels and Oils 255
 - 11.2.1 Analysis of Toxic Elements in Fuels 256
 - 11.2.1.1 Measurement Technology 256
 - 11.2.1.2 Analytical Performance 258
 - 11.2.2 Analysis of Additives in Lubricating Oils 258
 - 11.2.3 Identification of Abrasive Particles in Used Lubricants 260
 - 11.3 Trace Analysis in Liquids 261
 - 11.3.1 Analytical Task 261
 - 11.3.2 Preparation by Drying 261
 - 11.3.3 Quantification 262
 - 11.4 Special Preparation Techniques for Liquid Samples 263
 - 11.4.1 Determination of Light Elements in Liquids 263
 - 11.4.2 Enrichment Through Absorption and Complex Formation 264
- 12 Trace Analysis Using Total Reflection X-Ray Fluorescence 267**
 - 12.1 Special Features of TXRF 267
 - 12.2 Sample Preparation for TXRF 269
 - 12.3 Evaluation of the Spectra 271
 - 12.3.1 Spectrum Preparation and Quantification 271
 - 12.3.2 Conditions for Neglecting the Matrix Interaction 272
 - 12.3.3 Limits of Detection 273
 - 12.4 Typical Applications of the TXRF 274
 - 12.4.1 Analysis of Aqueous Solutions 274
 - 12.4.1.1 Analytical Problem and Preparation Possibilities 274
 - 12.4.1.2 Example: Analysis of a Fresh Water Standard Sample 275
 - 12.4.1.3 Example: Detection of Mercury in Water 277
 - 12.4.2 Analysis of the Smallest Sample Quantities 278
 - 12.4.2.1 Example: Pigment Analysis 278

- 12.4.2.2 Example: Aerosol Analysis 279
- 12.4.2.3 Example: Analysis of Nanoparticles 279
- 12.4.3 Trace Element Analysis on Human Organs 280
- 12.4.3.1 Example: Analysis of Blood and Blood Serum 280
- 12.4.3.2 Example: Analysis of Trace Elements in Body Tissue 282
- 12.4.4 Trace Analysis of Inorganic and Organic Chemical Products 283
- 12.4.5 Analysis of Semiconductor Electronics 284
- 12.4.5.1 Ultra-Trace Analysis on Si Wafers with VPD 284
- 12.4.5.2 Depth Profile Analysis by Etching 285

- 13 Nonhomogeneous Samples 287**
- 13.1 Measurement Modes 287
- 13.2 Instrument Requirements 288
- 13.3 Data Evaluation 290

- 14 Coating Analysis 291**
- 14.1 Analytical Task 291
- 14.2 Sample Handling 292
- 14.3 Measurement Technology 293
- 14.4 The Analysis Examples of Coated Samples 294
- 14.4.1 Single-Layer Systems: Emission Mode 294
- 14.4.2 Single-Layer Systems: Absorption Mode 297
- 14.4.3 Single-Layer Systems: Relative Mode 298
- 14.4.3.1 Analytical Problem 298
- 14.4.3.2 Variation of the Specified Working Distance 298
- 14.4.3.3 Sample Size and Spot Size Mismatch 299
- 14.4.3.4 Non-detectable Elements in the Layer: NiP Layers 300
- 14.4.4 Characterization of Ultrathin Layers 302
- 14.4.5 Multilayer Systems 304
- 14.4.5.1 Layer Systems 304
- 14.4.5.2 Measurement Technology 305
- 14.4.5.3 Example: Analysis of CIGS Solar Cells 305
- 14.4.5.4 Example: Analysis of Solder Structures 306
- 14.4.6 Samples with Unknown Coating Systems 307
- 14.4.6.1 Preparation of Cross Sections 308
- 14.4.6.2 Excitation at Grazing Incidence with Varying Angles 309
- 14.4.6.3 Measurement in Confocal Geometry 311

- 15 Spot Analyses 313**
- 15.1 Particle Analyses 313
- 15.1.1 Analytical Task 313
- 15.1.2 Sample Preparation 314
- 15.1.3 Analysis Technology 315
- 15.1.4 Application Example: Wear Particles in Used Oil 315
- 15.1.5 Application Example: Identification of Glass Particles by Chemometrics 316
- 15.2 Identification of Inclusions 318

15.3	Material Identification with Handheld Instruments	318
15.3.1	Analytical Tasks	318
15.3.2	Analysis Technology	319
15.3.3	Sample Preparation and Test Conditions	320
15.3.4	Analytical Accuracy	320
15.3.5	Application Examples	321
15.3.5.1	Example: Lead in Paint	321
15.3.5.2	Example: Scrap Sorting	321
15.3.5.3	Example: Material Inspection and Sorting	322
15.3.5.4	Example: Precious Metal Analysis	322
15.3.5.5	Example: Prospecting and Screening in Geology	323
15.3.5.6	Example: Investigation of Works of Art	323
15.4	Determination of Toxic Elements in Consumer Products: RoHS Monitoring	324
15.4.1	Analytical Task	324
15.4.2	Analysis Technology	325
15.4.3	Analysis Accuracy	327
15.5	Toxic Elements in Toys: Toys Standard	328
15.5.1	Analytical Task	328
15.5.2	Sample Preparation	328
15.5.3	Analysis Technology	330
16	Analysis of Element Distributions	331
16.1	General Remarks	331
16.2	Measurement Conditions	332
16.3	Geology	333
16.3.1	Samples Types	333
16.3.2	Sample Preparation and Positioning	333
16.3.3	Measurements on Compact Rock Samples	334
16.3.3.1	Sum Spectrum and Element Distributions	334
16.3.3.2	Object Spectra	335
16.3.3.3	Treatment of Line Overlaps	336
16.3.3.4	Maximum Pixel Spectrum	339
16.3.4	Thin Sections of Geological Samples	340
16.4	Electronics	342
16.5	Archeometric Investigations	344
16.5.1	Analytical Tasks	344
16.5.2	Selection of an Appropriate Spectrometer	346
16.5.3	Investigations of Coins	347
16.5.4	Investigations of Painting Pigments	349
16.6	Homogeneity Tests	350
16.6.1	Analytical Task	350
16.6.2	Homogeneity Studies Using Distribution Analysis	351
16.6.3	Homogeneity Studies Using Multi-point Measurements	352
17	Special Applications of the XRF	355
17.1	High-Throughput Screening and Combinatorial Analysis	355

17.1.1	High-Throughput Screening	355
17.1.2	Combinatorial Analysis for Drug Development	357
17.2	Chemometric Spectral Evaluation	358
17.3	High-Resolution Spectroscopy for Speciation Analysis	361
17.3.1	Analytical Task	361
17.3.2	Instrument Technology	361
17.3.3	Application Examples	362
17.3.3.1	Analysis of Different Sulfur Compounds	362
17.3.3.2	Speciation of Aluminum Inclusions in Steel	363
17.3.3.3	Determination of SiO ₂ in SiC	365
18	Process Control and Automation	367
18.1	General Objectives	367
18.2	Off-Line and At-Line Analysis	369
18.2.1	Sample Supply and Analysis	369
18.2.2	Automated Sample Preparation	371
18.3	In-Line and On-Line Analysis	376
19	Quality Management and Validation	379
19.1	Motivation	379
19.2	Validation	380
19.2.1	Parameters	384
19.2.2	Uncertainty	385
Appendix A Tables 387		
Appendix B Important Information 419		
B.1	Coordinates of Main Manufacturers of Instruments and Preparation Tools	419
B.2	Main Suppliers of Standard Materials	422
B.2.1	Geological Materials and Metals	422
B.2.2	Stratified Materials	423
B.2.3	Polymer Standards	424
B.2.4	High Purity Materials	424
B.2.5	Precious Metal Alloys	425
B.3	Important Websites	425
B.3.1	Information About X-Ray Analytics and Fundamental Parameters	425
B.3.2	Information About Reference Materials	426
B.3.3	Scientific Journals	427
B.4	Laws and Acts, Which Are Important for X-Ray Fluorescence	427
B.4.1	Radiation Protection	427
B.4.2	Regulations for Environmental Control	428
B.4.3	Regulations for Performing Analysis	428
B.4.4	Use of X-ray Fluorescence for the Chemical Analysis	428
B.4.4.1	General Regulations	428

B.4.4.2	Analysis of Minerals	429
B.4.4.3	Analysis of Oils, Liquid Fuels, Grease	430
B.4.4.4	Analysis of Solid Fuels	432
B.4.4.5	Coating Analysis	433
B.4.4.6	Metallurgy	433
B.4.4.7	Analysis of Electronic Components	434

References	435
-------------------	-----

Index	453
--------------	-----