

Contents

Preface.....	ix
Acknowledgments.....	xiv
Author	xv
Chapter 1 Basics of Drilling and Drilling System.....	1
1.1 Basic Drilling Operations.....	1
1.2 Machining Regime in Drilling Operations	5
1.2.1 Cutting Speed.....	5
1.2.2 Feed, Feed per Tooth, and Feed Rate.....	5
1.2.3 Depth of Cut and Material Removal Rate.....	7
1.2.4 Cut and Its Dimensions	8
1.2.5 Selecting Machining Regime: General Idea	11
1.2.6 Cutting Force and Power in Drilling Operations	14
1.3 Drilling System	15
1.3.1 System Concept.....	15
1.3.2 Structure of the Drilling System	16
1.3.3 Coherency Law.....	17
1.3.4 System Objective.....	18
1.4 Concept of Cutting Tool Quality	21
1.5 Case for HP Drills	22
1.6 Design of Drilling Systems	25
1.6.1 Part Drawing Analysis and Design of the Tool Layout.....	26
1.6.2 Drill Selection	29
1.6.3 HP Drill Design/Geometry Selection	32
References	33
Chapter 2 Geometry and Design Components of Drilling Tools	35
2.1 Drills.....	35
2.1.1 Classification	35
2.1.2 Nomenclature/Terminology	41
2.1.3 Design and Geometry: Advanced Users' Perspective.....	45
2.1.4 Microgeometry	106
2.1.5 Tool Design/Development/Research Perspective	120
2.1.6 Generalization	226
2.2 Reamers	228
2.2.1 Definition and Current ISO Standards.....	228
2.2.2 General Classification	230
2.2.3 Nomenclature/Terminology of Reamer Elements and Associated Terms	232
2.2.4 Basic Reamers Geometry and Its Relevant Particularities	233
2.2.5 Trends in the Development.....	241
2.2.6 Process and Design Parameters to Consider	243
2.3 Taps.....	244
2.3.1 Introduction Words.....	244
2.3.2 Definition of Tapping and Tap.....	245

2.3.3	Classification	245
2.3.4	Nomenclature	245
2.3.5	Taps Cutting Geometry	248
2.3.6	Thread Profile and Tolerances.....	254
2.3.7	Methodology to Calculate the Drilling Tool Diameter for Tap Holes	258
2.3.8	Synchronization Issue in Tapping	262
2.3.9	Some Notes on Thread Formers/Forming Taps.....	264
	References	268
Chapter 3	Deep-Hole Drilling Tools.....	273
3.1	Introduction	273
3.2	Common Classification of Deep-Hole Machining Operations	273
3.3	Gundrills: Basic Design and Geometry.....	275
3.3.1	History.....	276
3.3.2	Common Design and Geometry: Advanced Users’ Perspective.....	277
3.3.3	Tool Design/Development/Research Perspective	300
3.4	STS Drills.....	319
3.4.1	Short History	320
3.4.2	Basic Operations.....	321
3.4.3	Force Balance	324
3.4.4	Basic Geometry of STS Drills	328
3.4.5	Power and Force	330
3.4.6	Problem with the Core.....	333
3.4.7	Problem with the Pressure Distribution	335
3.4.8	Addressing the Problems with the Pressure Distribution and the Core	338
3.5	Ejector Drills	339
	References	351
Chapter 4	PCD Drilling Tools	353
4.1	Challenges of Work Materials – Why Diamond as a Tool Material is Needed?.....	353
4.1.1	MMCs.....	353
4.1.2	CFRP.....	354
4.1.3	Diamond Tool as the Most Feasible Option	355
4.1.4	Application Particularities.....	356
4.2	Diamond: Word Origin and Early History	356
4.3	Structure and Important Properties.....	358
4.3.1	Structure and Bonding in Graphite and Diamond	358
4.3.2	Important Properties	361
4.4	Applications.....	362
4.5	Types.....	363
4.6	Synthetic Diamond	363
4.6.1	History.....	363
4.6.2	Synthetic Diamond Brief Classification	364
4.6.3	Synthetic Diamond Technology: High-Pressure Equipment	364
4.6.4	Synthetic Diamond Technology: The Synthesis	365

4.7	Blanks for Drilling Tools.....	366
4.7.1	PDC and PCD	366
4.7.2	Available PCD Blanks/Disk.....	370
4.7.3	Manufacturing of PCD Disks.....	372
4.7.4	Powder Mix	375
4.7.5	Grain Size.....	378
4.7.6	Interfaces	382
4.7.7	Quality Control.....	383
4.8	Thermal Stability.....	386
4.8.1	Effect of Temperature on PCD Structure.....	386
4.8.2	Improving Thermal Stability of PCDs.....	387
4.8.3	PCD Overheating – Results.....	390
4.8.4	PCD Overheating – Causes	391
4.9	Brazing	392
4.9.1	Examples of Poor Brazing.....	394
4.9.2	Literature Support	394
4.9.3	Factors to be Considered	395
4.10	Roughing/Trimming and Finishing	400
4.10.1	EDM	400
4.10.2	Electric Discharge Grinding	403
4.10.3	Laser Cutting of PCD.....	405
4.10.4	Abrasive Grinding	408
4.11	PCD Drilling Tools Design	408
4.11.1	PCD-Tipped Drilling Tools.....	408
4.11.2	Full-Face (Cross) PCD Drills	414
4.11.3	Full-Head PCD Drills	423
	References	424
Appendix	Basics of the Tool Geometry	430
A.1	Basic Terms and Definitions.....	430
A.1.1	Workpiece Surfaces.....	430
A.1.2	Tool Surfaces and Elements	432
A.1.3	Types of Cutting	433
A.1.4	Important Nomenclature of a Single-Point Tool	434
A.2	Systems of Consideration of the Cutting Tool Geometry	437
A.2.1	Standard and Proposed Systems	437
A.2.2	What Does It Mean “The Tool Geometry”?	438
A.3	Reference System	438
A.3.1	General	438
A.3.2	Reference Plane	439
A.4	Tool-in-Hand System (T-hand-S)	440
A.4.1	Reference Plane, P_r	440
A.4.2	Working Plane, P_f	441
A.4.3	Back Plane, P_p	443
A.4.4	Tool Cutting Edge Plane, P_s	444
A.4.5	Tool Orthogonal, P_o and Tool Normal, P_n Planes	444
A.4.6	Reference System for the Minor Cutting Edge	444
A.4.7	Angles in the Reference Plane P_r	445
A.4.8	Angles in the Working and Back Planes	448
A.4.9	Angles in the Orthogonal Plane	450

A.4.10 Angles in the Cutting Edge and Normal Planes 451

A.4.11 Minor Cutting Edge 452

A.4.12 Geometrical Relationship Among Angles in T-hand-S 452

A.4.13 Drilling Tool Geometry in T-hand-S 454

A.5 Tool-in-Holder System (T-hold-S)..... 456

A.6 Tool-in-Machine System (T-mach-S) 457

A.7 Tool-in-Use System (T-use-S) 458

A.7.1 T-use-S Reference Planes..... 458

A.7.2 T-use-S Angles 458

A.8 Importance of the Introduced Angles 462

A.8.1 Clearance Angle..... 462

A.8.2 Rake Angle..... 467

A.8.3 Tool Cutting Edge Angle..... 471

A.8.4 Minor Cutting Edge 472

A.8.5 Inclination Angle..... 475

References 476

Index..... 479