

Contents

About the Author	xv
Foreword	xvii
Series Preface	xix
Preface to the Second Edition	xxi
Preface to the First Edition	xxiii
1 Introduction	1
1.1 Definition and History of Tribology	1
1.2 Industrial Significance of Tribology	3
1.3 Origins and Significance of Micro/Nanotribology	4
1.4 Organization of the Book	6
References	7
2 Solid Surface Characterization	9
2.1 The Nature of Surfaces	9
2.2 Physico-Chemical Characteristics of Surface Layers	10
2.2.1 <i>Deformed Layer</i>	10
2.2.2 <i>Chemically Reacted Layer</i>	11
2.2.3 <i>Physisorbed Layer</i>	12
2.2.4 <i>Chemisorbed Layer</i>	13
2.2.5 <i>Methods of Characterization of Surface Layers</i>	13
2.3 Analysis of Surface Roughness	14
2.3.1 <i>Average Roughness Parameters</i>	16
2.3.2 <i>Statistical Analyses</i>	23
2.3.3 <i>Fractal Characterization</i>	45
2.3.4 <i>Practical Considerations in Measurement of Roughness Parameters</i>	47
2.4 Measurement of Surface Roughness	51
2.4.1 <i>Mechanical Stylus Method</i>	52
2.4.2 <i>Optical Methods</i>	56
2.4.3 <i>Scanning Probe Microscopy (SPM) Methods</i>	67
2.4.4 <i>Fluid Methods</i>	76
2.4.5 <i>Electrical Method</i>	77
2.4.6 <i>Electron Microscopy Methods</i>	77

2.4.7	<i>Analysis of Measured Height Distribution</i>	78
2.4.8	<i>Comparison of Measurement Methods</i>	78
2.5	Closure	84
	Problems	85
	References	86
	Further Reading	88
3	Contact Between Solid Surfaces	91
3.1	Introduction	91
3.2	Analysis of the Contacts	92
3.2.1	<i>Single Asperity Contact of Homogeneous and Frictionless Solids</i>	92
3.2.2	<i>Single Asperity Contact of Layered Solids in Frictionless and Frictional Contacts</i>	105
3.2.3	<i>Multiple Asperity Dry Contacts</i>	117
3.3	Measurement of the Real Area of Contact	146
3.3.1	<i>Measurement Techniques</i>	146
3.3.2	<i>Typical Measurements</i>	147
3.4	Closure	150
	Problems	152
	References	153
	Further Reading	155
4	Adhesion	157
4.1	Introduction	157
4.2	Solid–Solid Contact	158
4.2.1	<i>Covalent Bond</i>	161
4.2.2	<i>Ionic or Electrostatic Bond</i>	161
4.2.3	<i>Metallic Bond</i>	162
4.2.4	<i>Hydrogen Bond</i>	164
4.2.5	<i>van der Waals Bond</i>	164
4.2.6	<i>Free Surface Energy Theory of Adhesion</i>	164
4.2.7	<i>Polymer Adhesion</i>	171
4.3	Liquid-Mediated Contact	172
4.3.1	<i>Idealized Geometries</i>	173
4.3.2	<i>Multiple-Asperity Contacts</i>	186
4.4	Closure	194
	Problems	195
	References	195
	Further Reading	197
5	Friction	199
5.1	Introduction	199
5.2	Solid–Solid Contact	201
5.2.1	<i>Rules of Sliding Friction</i>	201
5.2.2	<i>Basic Mechanisms of Sliding Friction</i>	206

5.2.3	<i>Other Mechanisms of Sliding Friction</i>	222
5.2.4	<i>Friction Transitions During Sliding</i>	224
5.2.5	<i>Static Friction</i>	226
5.2.6	<i>Stick-Slip</i>	228
5.2.7	<i>Rolling Friction</i>	232
5.3	Liquid-Mediated Contact	236
5.4	Friction of Materials	239
5.4.1	<i>Friction of Metals and Alloys</i>	240
5.4.2	<i>Friction of Ceramics</i>	244
5.4.3	<i>Friction of Polymers</i>	248
5.4.4	<i>Friction of Solid Lubricants</i>	254
5.5	Closure	264
	Problems	266
	References	267
	Further Reading	271
6	Interface Temperature of Sliding Surfaces	273
6.1	Introduction	273
6.2	Thermal Analysis	274
6.2.1	<i>Fundamental Heat Conduction Solutions</i>	275
6.2.2	<i>High Contact-Stress Condition ($A_r/A_a \sim 1$) (Individual Contact)</i>	276
6.2.3	<i>Low Contact-Stress Condition ($A_r/A_a \ll 1$) (Multiple Asperity Contact)</i>	284
6.3	Interface Temperature Measurements	298
6.3.1	<i>Thermocouple and Thin-Film Temperature Sensors</i>	298
6.3.2	<i>Radiation Detection Techniques</i>	302
6.3.3	<i>Metallographic Techniques</i>	308
6.3.4	<i>Liquid Crystals</i>	308
6.4	Closure	309
	Problems	311
	References	312
7	Wear	315
7.1	Introduction	315
7.2	Types of Wear Mechanism	316
7.2.1	<i>Adhesive Wear</i>	316
7.2.2	<i>Abrasive Wear (by Plastic Deformation and Fracture)</i>	328
7.2.3	<i>Fatigue Wear</i>	342
7.2.4	<i>Impact Wear</i>	349
7.2.5	<i>Chemical (Corrosive) Wear</i>	359
7.2.6	<i>Electrical-Arc-Induced Wear</i>	361
7.2.7	<i>Fretting and Fretting Corrosion</i>	363
7.3	Types of Particles Present in Wear Debris	365
7.3.1	<i>Plate-Shaped Particles</i>	365
7.3.2	<i>Ribbon-Shaped Particles</i>	366

7.3.3	<i>Spherical Particles</i>	367
7.3.4	<i>Irregularly Shaped Particles</i>	367
7.4	Wear of Materials	369
7.4.1	<i>Wear of Metals and Alloys</i>	371
7.4.2	<i>Wear of Ceramics</i>	376
7.4.3	<i>Wear of Polymers</i>	383
7.5	Closure	388
	Problems	391
	References	392
	Further Reading	396
8	Fluid Film Lubrication	399
8.1	Introduction	399
8.2	Regimes of Fluid Film Lubrication	400
8.2.1	<i>Hydrostatic Lubrication</i>	401
8.2.2	<i>Hydrodynamic Lubrication</i>	401
8.2.3	<i>Elastohydrodynamic Lubrication</i>	402
8.2.4	<i>Mixed Lubrication</i>	403
8.2.5	<i>Boundary Lubrication</i>	403
8.3	Viscous Flow and Reynolds Equation	404
8.3.1	<i>Viscosity and Newtonian Fluids</i>	404
8.3.2	<i>Fluid Flow</i>	409
8.4	Hydrostatic Lubrication	418
8.5	Hydrodynamic Lubrication	428
8.5.1	<i>Thrust Bearings</i>	430
8.5.2	<i>Journal Bearings</i>	443
8.5.3	<i>Squeeze Film Bearings</i>	462
8.5.4	<i>Gas-Lubricated Bearings</i>	465
8.6	Elastohydrodynamic Lubrication	481
8.6.1	<i>Forms of Contacts</i>	482
8.6.2	<i>Line Contact</i>	483
8.6.3	<i>Point Contact</i>	490
8.6.4	<i>Thermal Correction</i>	491
8.6.5	<i>Lubricant Rheology</i>	491
8.7	Closure	493
	Problems	495
	References	497
	Further Reading	499
9	Boundary Lubrication and Lubricants	501
9.1	Introduction	501
9.2	Boundary Lubrication	501
9.2.1	<i>Effect of Adsorbed Gases</i>	505
9.2.2	<i>Effect of Monolayers and Multilayers</i>	505
9.2.3	<i>Effect of Chemical Films</i>	508
9.2.4	<i>Effect of Chain Length (or Molecular Weight)</i>	510

9.3	Liquid Lubricants	511
9.3.1	<i>Principal Classes of Lubricants</i>	511
9.3.2	<i>Physical and Chemical Properties of Lubricants</i>	517
9.3.3	<i>Additives</i>	517
9.4	Greases	520
9.5	Closure	521
	References	521
	Further Reading	522
10	Nanotribology	525
10.1	Introduction	525
10.2	SFA Studies	527
10.2.1	<i>Description of an SFA</i>	528
10.2.2	<i>Static (Equilibrium), Dynamic and Shear Properties of Molecularly Thin Liquid Films</i>	530
10.3	AFM/FFM Studies	538
10.3.1	<i>Description of AFM/FFM and Various Measurement Techniques</i>	539
10.3.2	<i>Surface Imaging, Friction, and Adhesion</i>	547
10.3.3	<i>Wear, Scratching, Local Deformation, and Fabrication/Machining</i>	566
10.3.4	<i>Indentation</i>	577
10.3.5	<i>Boundary Lubrication</i>	583
10.4	Atomic-Scale Computer Simulations	598
10.4.1	<i>Interatomic Forces and Equations of Motion</i>	598
10.4.2	<i>Interfacial Solid Junctions</i>	599
10.4.3	<i>Interfacial Liquid Junctions and Confined Films</i>	601
10.5	Closure	602
	References	606
	Further Reading	612
11	Friction and Wear Screening Test Methods	615
11.1	Introduction	615
11.2	Design Methodology	615
11.2.1	<i>Simulation</i>	616
11.2.2	<i>Acceleration</i>	616
11.2.3	<i>Specimen Preparation</i>	616
11.2.4	<i>Friction and Wear Measurements</i>	617
11.3	Typical Test Geometries	619
11.3.1	<i>Sliding Friction and Wear Tests</i>	619
11.3.2	<i>Abrasion Tests</i>	623
11.3.3	<i>Rolling-Contact Fatigue Tests</i>	625
11.3.4	<i>Solid-Particle Erosion Test</i>	625
11.3.5	<i>Corrosion Tests</i>	626

11.4	Closure	628
	References	628
	Further Reading	629
12	Tribological Components and Applications	631
12.1	Introduction	631
12.2	Common Tribological Components	631
	<i>12.2.1 Sliding-Contact Bearings</i>	631
	<i>12.2.2 Rolling-Contact Bearings</i>	633
	<i>12.2.3 Seals</i>	635
	<i>12.2.4 Gears</i>	637
	<i>12.2.5 Cams and Tappets</i>	640
	<i>12.2.6 Piston Rings</i>	641
	<i>12.2.7 Electrical Brushes</i>	643
12.3	MEMS/NEMS	644
	<i>12.3.1 MEMS</i>	647
	<i>12.3.2 NEMS</i>	653
	<i>12.3.3 BioMEMS</i>	654
	<i>12.3.4 Microfabrication Processes</i>	655
12.4	Material Processing	656
	<i>12.4.1 Cutting Tools</i>	656
	<i>12.4.2 Grinding and Lapping</i>	660
	<i>12.4.3 Forming Processes</i>	661
	<i>12.4.4 Cutting Fluids</i>	661
12.5	Industrial Applications	662
	<i>12.5.1 Automotive Engines</i>	663
	<i>12.5.2 Gas Turbine Engines</i>	664
	<i>12.5.3 Railroads</i>	668
	<i>12.5.4 Magnetic Storage Devices</i>	669
12.6	Closure	676
	References	676
	Further Reading	680
13	Green Tribology and Biomimetics	683
13.1	Introduction	683
13.2	Green Tribology	683
	<i>13.2.1 Twelve Principles of Green Tribology</i>	684
	<i>13.2.2 Areas of Green Tribology</i>	685
13.3	Biomimetics	689
	<i>13.3.1 Lessons from Nature</i>	690
	<i>13.3.2 Industrial Significance</i>	693
13.4	Closure	693
	References	694
	Further Reading	696

Appendix A Units, Conversions, and Useful Relations	697
A.1 Fundamental Constants	697
A.2 Conversion of Units	698
A.3 Useful Relations	698
Index	701