CONTENTS

1. Introduction	(
2. Sources of defects	
2.1. Higher requirements on thermal protection of buildings 2.2. Permeable inner deck 2.3. Insufficiently ventilated air layer 2.4. Outer deck with insignificant thermal inertia and resistance	16 17
3. Calculation procedures	17
4. Recommended solutions	18
References	19
Curriculum vitae	21