

Table of content

1. State of Art – Nondestructive Testing	4
1.1 Introduction	4
2. Nondestructive Testing	5
2.1 Ultrasound Pulse velocity Method	5
2.1.1 Mechanical property prediction	5
2.1.2 Influence of member dimension	7
2.1.3 Influence of wood structure	7
2.1.4 Influence of environmental conditions	7
2.1.5 Influence of coupling agents	8
2.1.6 Deterioration detection	9
2.2 Resistance Drilling	9
2.2.1 Mechanical property prediction	10
2.2.2 Deterioration detection	11
2.2.3 Factors influencing the measurements	11
2.3 Pilodyn Method	12
2.3.1 Density prediction	12
2.3.2 Mechanical property prediction	13
2.3.3 Influence of material properties and decay assessment	13
2.4 Conclusions of Nondestructive Methods	13
3. Methodic	15
3.1 Material and Methodology	15
3.2 Density Determination	19
3.3 Test procedures	19
3.3.1 Ultrasound Pulse velocity Method	19
3.3.2 Resistance Drilling	20
3.3.3 Pilodyn Method	21
4. Results and analysis	22
4.1 Ultrasound Pulse velocity Method	22
4.2 Resistance Drilling	27
4.3 Pilodyn Method	30
5. Concluding Remarks	35
6. Reference	36