

Content

Content	7
Foreword	11
1 Introduction	15
1.1 Cultural Heritage and Floods	18
1.2. Cultural heritage endangered by Floods	22
1.3 Floods	
2 Cultural Heritage in Flood prone areas	27
2.1 Typical damage of cultural heritage in relation to flood events	27
2.1.1 Flood impact on buildings and foundations	28
2.1.2 Impact of floods on cities and heritage sites	32
2.1.3 Impact of floods on moveable cultural heritage items	34
2.2 Vulnerability of cultural heritage	39
2.2.1 Immoveable heritage	39
2.2.2 Moveable heritage	40
2.2.3 Examples of material parameters characterizing the vulnerability of immoveable heritage	41
2.2.4 Recommendations	43
2.3 Stock-at risk-mapping	44

3	Measures	51
3.1	Before flooding: Damage prevention and mitigation	52
3.1.1	Administrative measures	52
3.1.2	Practical measures	55
3.1.3	Identifying the individual risk of cultural heritage objects (examples), flood diagnosis	56
3.1.4	Traditional means / instruments of prevention: dykes, retention areas, suitable use of buildings	57
3.1.5	Recommendations	60
3.2	During a flood	62
3.2.1	Introduction	62
3.2.2	Rescue action during a flood event	63
3.2.3	National and international cooperation	64
3.2.4	First-Aid Measures	65
3.2.5	Recommendations	65
3.3	After the flood	66
3.3.1	Introduction	66
3.3.2	Restoration and repair techniques for moveable objects and materials	67
3.3.3	Restoration and repair techniques for immovable objects and materials	68
3.3.4	Emergency action after flooding of immovable heritage	73
4	Examples and Case studies	75
4.1	Historic houses	75
4.1.1	House in Prague-Podhoří (Czech Republic)	75
4.1.2	General repair practice	77
4.2	Historic towns	79
4.2.1	Genoa (Italy) - flash floods	79
4.2.2	Regensburg (Germany) - large-river flood in a historic city	83
4.2.3	Praha (Czech Republic) - large-river flood in a historic district	88
4.2.4	Dresden (Germany) - a large-river flood in a historic city	93
4.2.5	Grimma (Germany) - a small-river flood in a small walled town	97
4.2.6	Český Krumlov (Czech Republic) - a small-river flood in a small town	103
4.2.7	Švihov (Czech Republic) - a small-river flood in a town with a water fortress	107
4.3	Gardens / parks	111
4.3.1	Pillnitz Castle (Germany) - park and museum	111
4.3.2	Jaroměřice nad Rokytnou Castle (Czech Republic) - a cultural heritage park and garden	115
4.3.3	Veltrusy Castle (Czech Republic) - landscape park and sculptures	117
4.4	Stone Bridges	122
4.4.1	Medieval stone bridge in Písek (Bohemia, Czech Republic)	122
4.4.2	Lessons on the flood resistance of historic stone arch bridges	128
4.5	Archives / libraries	130
4.5.1	Archive of architectural plans in Prague (Czech Republic)	130
4.6	Museum objects	133
4.6.1	The “Mirakelmann” - Miracle Man (Germany)	133
4.6.2	Archbishop’s carriage - National Museum in Prague (Czech Republic)	135
4.6.3	Chemical composition of commercial agents	137
4.7	Heritage sites	138
4.7.1	Terezín (Czech Republic) - bulwark water fortress	138
4.7.2	Piran (Slovenia) - The Church of Our Lady of Health, threatened by sea-flooding	142
4.7.3	Harcov (Czech Republic) - historic dam retrofitting	147

5 Conclusions: General recommendations	151
5.1 General	151
5.2 Raising awareness of flood hazards and vulnerability	152
5.3 Recommendations on administration and management	153
5.4 Selecting appropriate measures	154
5.5 Lessons learnt from case studies	156
6 Index	159
6.1 References	159
6.2 Glossary	164
6.3 Contact addresses	168
6.4 List of deliverables	171
6.5 Acknowledgement	181
7 Annexes	183
7.1 Information sheets / leaflets for Emergency preparedness	183
7.2 Damage database	185
7.2.1 Introduction	185
7.2.2 Related work	185
7.2.3 Description of the knowledge base	186
7.2.4 Information system	187
7.2.5 Future work and conclusions	190
7.2.6 Input form for a failure case	191
7.2.7 Meaning of the form fields	193
7.2.8 Illustrative database outputs on failures of immovable cultural heritage	195
7.3 Effects of flooding on material behaviour	196
7.3.1 Material parameters	196
7.3.2 Laboratory tests on typical historical materials	199
7.4 Non-destructive methods for assessing moisture in masonry	204
7.4.1 Quantitative minor-destructive methods	205
7.4.2 Quantitative non-destructive techniques	205
7.4.3 Qualitative non-destructive techniques	208
7.5 Effects of floods on masonry walls: NDTs for measuring drying rates	212
7.6 Example - Flood risk mapping	221
7.7 An example of cultural heritage emergency management after an earthquake	224

