

Table of Contents

1	Introduction.....	1
	<i>L. J. A. Heitz-Mayfield, U. Brägger</i>	
2	Literatur Review	3
	<i>L. J. A. Heitz-Mayfield, U. Brägger</i>	
2.1	Statements and Recommendations Obtained from the 4th and 5th ITI Consensus Conferences	4
2.1.1	Proceedings of the 4th ITI Consensus Conference 2008	4
2.1.2	Proceedings of the 5th ITI Consensus Conference 2013	5
2.2	Literature Review: Biological Complications.....	10
	<i>L. J. A. Heitz-Mayfield</i>	
2.3	Literature Review: Hardware Complications and Failures	12
	<i>U. Brägger</i>	
2.3.1	Mechanical and Technical Risks	12
2.3.2	Effect of Improved Components on Complications and Failure Rates	12
2.3.3	Complication and Failure Rates with Cemented versus Screw-retained Reconstructions.....	13
2.3.4	Complication and Failure Rates with Metal versus Ceramic Abutments	14
2.3.5	State of the Art of CAD/CAM-assisted Production of Implant-supported Reconstructions	14
2.3.6	Overdentures.....	14
2.3.7	Survival Rates of Reconstructions Obtained from Systematic Reviews	15
3	Etiology and Risk Factors: Biological Complications	17
	<i>L. J. A. Heitz-Mayfield</i>	
3.1	Peri-implant Infections.....	18
3.1.1	Peri-implant Biofilms	20
3.1.2	Risk Factors for Peri-implant Infection	21
3.1.3	Hardware Complications Presenting as Biological Complications.....	24
3.2	Non-plaque-related Biological Complications	26
3.2.1	Complete Loss of Osseointegration and Occlusal Overload.....	26
3.2.2	Other Theories for the Etiology of Loss of Osseointegration.....	27
3.2.3	Non-plaque-related Oral Mucosal Disorders	27

4	Etiology and Origin of Hardware Complications	29
	<i>U. Brägger</i>	
4.1	Materials and Interfaces.....	30
4.2	Absorption of Kinetic Energy and Biomechanical Risks.....	32
4.3	Hardware-related Complications and Failures	34
4.3.1	Implant Body.....	34
4.3.2	Implant Body/Abutment Interface	34
4.3.3	Abutment Screw.....	34
4.3.4	Abutment Body	35
4.3.5	Retention of Superstructures: Screw-retained and Cemented.....	35
4.3.6	Closure Screws, Healing Abutments, Mucosa Formers	36
4.3.7	Attachment System for Overdentures.....	36
4.3.8	Mesostructures.....	36
4.3.9	Reconstruction.....	37
5	Management of Biological Complications.....	39
	<i>L. J. A. Heitz-Mayfield</i>	
5.1	Treatment of Peri-implant Mucositis	40
5.2	Treatment of Peri-implantitis.....	42
5.2.1	Pre-treatment Phase	42
5.2.2	Non-surgical Debridement.....	43
5.2.3	Early Reassessment.....	44
5.2.4	Surgical Intervention.....	44
5.2.5	Immediate Postsurgical Care	49
5.2.6	Maintenance	49
5.2.7	Implant Removal.....	49
5.2.8	Concluding Remarks	51
5.3	Non-plaque-related Biological Complications	52
6	Management of Hardware Complications.....	53
	<i>U. Brägger</i>	
6.1	Hardware Complications	54
6.1.1	Fracture and Loss of Implants.....	54
6.1.2	Unfavorable Three-dimensional Position of the Platform	58
6.1.3	Complications Related to Abutments	61
6.1.4	Complications Related to Abutment Screws.....	63
6.1.5	Complications Related to Retention	70
6.1.6	Complications Related to Healing Abutments	78
6.1.7	Complications Related to Systems for Overdentures.....	80
6.2	Superstructure-related Complications.....	83
6.2.1	Denture Teeth and Acrylic	83
6.2.2	Wear and Attrition.....	84
6.2.3	Ceramic Chipping.....	85
6.3	Iatrogenic Reasons	86

7	Prevention of Biological Complications.....	89
	<i>L. J. A. Heitz-Mayfield</i>	
7.1	Prevention of Peri-implant Infections	90
7.1.1	Treatment Planning	91
7.1.2	Preparation of the Patient	91
7.1.3	Preparation of the Recipient Site.....	92
7.1.4	Implant Placement.....	93
7.1.5	Prosthesis Design	95
7.1.6	Supportive Care.....	98
7.1.7	Diagnostic Monitoring of the Peri-implant Tissues.....	99
7.1.8	Frequency of Recall.....	100
7.2	Prevention of Loss of Osseointegration Due to Occlusal Overload.....	101
7.3	Prevention of Non-plaque-related Oral Mucosal Disorders.....	102
7.4	Concluding Remarks	103
8	Prevention of Hardware Complications.....	105
	<i>U. Brägger</i>	
8.1	Prevention of Complications Related to Components and Reconstructions	106
8.1.1	Implant Body.....	106
8.1.2	Implant/Abutment Connection	107
8.1.3	Abutment Body and Abutment Screw.....	107
8.1.4	Third-party Components	107
8.1.5	Retention: Screw-retained and Cemented	108
8.1.6	Closure Screw, Healing Abutment, Mucosa Formers	109
8.1.7	Attachment Systems for Overdentures	109
8.1.8	Mesostructures.....	110
8.1.9	Superstructures	110
8.2	Risk Management	111
9	Clinical Case Presentations.....	115
	Biological Complications	
9.1.1	Iatrogenic Complications Managed by Replacing Prosthetic Components: Non-surgical Approach	116
	<i>B. Schmid</i>	
9.1.2	Peri-implantitis Treated with Access-Flap Surgery.....	120
	<i>L. J. A. Heitz-Mayfield</i>	
9.1.3	Excess Cement Resulting in Peri-implant Infection Presenting as a Draining Sinus Tract	123
	<i>T. Linkevičius</i>	

9.1.4 Peri-implantitis Modified by Submucosal Excess of Cement: Regenerative Peri-implantitis Therapy and Six-year Follow-up.....	127
<i>G. E. Salvi</i>	
9.1.5 Peri-implantitis Treated by an Antimicrobial and Regenerative Approach.....	131
<i>A. Mombelli, P. Wick</i>	
9.1.6 Recurrent Peri-implantitis Leading to Implant Removal.....	134
<i>L. J. A. Heitz-Mayfield</i>	
Biological Complications (Other than Infections)	
9.2.1 Removal of a Malpositioned Implant and Direct New Implant Placement with Simultaneous Contour Augmentation using GBR.....	136
<i>D. Buser, U. Belser</i>	
9.2.2 Oral Lichen Planus Associated with the Peri-implant Mucosa.....	147
<i>A. Frydrych</i>	
9.2.3 Peri-implant Carcinoma	149
<i>M. Moergel, P. W. Kämmerer, B. Al-Nawas</i>	
9.2.4 Peripheral Giant-cell Granuloma Associated with Peri-implant Tissues	153
<i>M. M. Bornstein</i>	
9.2.5 Peri-implantitis Resulting in Bisphosphonate-related Osteonecrosis of the Jaw	158
<i>M. M. Bornstein</i>	
9.2.6 Metal Allergy	164
<i>D. Wismeijer, D. Kruger, J. Muris</i>	
Hardware Complications	
9.3.1 Management of a Fractured Implant Supporting a Screw-retained Metal-ceramic Restoration	167
<i>H. P. Weber, A. Grous</i>	
9.3.2 Retreatment of a Patient with Multiple Biological and Technical Complications and Failures.....	171
<i>S. Hicklin, S. Tettamanti, U. Brägger</i>	
9.3.3 Management of a Technical Complication Caused by a Fractured Zirconia Abutment.....	179
<i>T. Joda, U. Brägger</i>	
9.3.4 Repeated Acrylic Fractures on a Mandibular Fixed Full-arch Implant-supported Metal/Acrylic Prosthesis	184
<i>J. Kan</i>	

10 Etiology, Management, and Prevention of Hardware Complications with Implant-supported Reconstructions 189
U. Brägger, S. Hicklin

11 Conclusions..... 197
L. J. A. Heitz-Mayfield, U. Brägger

12 References 199