

Contents

Preface

Summary of Proceedings

Summary of Discussion

SALT DAMAGE AND ANALYTICAL ISSUES

United Kingdom 23

Linking Studies of Salt Weathering in the Natural Environment with Cultural Heritage Conservation

H.A. Viles, A.S. Goudie

United States of America 31

Salts in the Deterioration of Porous Materials: A Call for the Right Questions

A.E. Charola, J. Pühringer

Italy 33

Damage Caused to Masonry by Salt Crystallisation: Experimental Research and Probabilistic Approach

State of the art report on Italian research

L. Binda, G. Cardani

Croatia 55

Salt Damage in Wall Paintings Damage in Wall Paintings (Typical salt problems in Croatia)

I. Srša, D. Krstić, D. Mudronja

Czech Republic 97

Gypsum – an Overlooked Corrosive Factor of Some Silicate Sandstones in Czech Republic

K. Bayer

Switzerland 109

Quantitative Salt Analysis in Conservation of Buildings

C. Bläuer Böhm

Denmark 111

Salt, Damp and Heat in Tirsted Church

P. Klenz-Larsen

Slovak Republik 119

Short Overview on Problematics of Watersoluble Salts in Slovak Republic

M. Stillhammerová

MODELLING AND MITIGATION

United States of America 127

The Damage Mechanism of Sodium Sulfate in Porous Stone

E. Doehne

Switzerland 147

Hydration Pressure: A Bad Case of Crystallization Pressure

R.J. Flatt

Germany	161
Properties of Salt Mixtures: Theory and Modelling M. Steiger	
Greece	163
The Solid/Solution Interface: Relevance to the Damage, Protection and the Restoration of Calcitic Marbles D.G. Kanellopoulou, M.G. Orkoulou, P.G. Koutsoukos	
Czech Republic	197
Coupled Moisture and Salt Transport in Building Materials: Theoretical and Experimental Treatments R. Černý, Z. Pavlík, P. Rovnaníková	
Finland	213
Salt Deterioration in Brick Walls and the Kinetics of Salt Transformation Analysed in situ in a Fortress Building of the 18th Century T. von Konow	
United Kingdom	225
The Kinetics of Salt Weathering of Porous Materials A. Sawdy, C. Price	
Poland	239
Climate Control for the Passive Mitigation of the Salt Damage R. Kozłowski	
Germany	245
Climate Controlled Weathering of Porous Structures by Soluble Salts S. Laue	
DESALINATION AND TREATMENT	
France	249
Desalination of Porous Building Materials: a Review V. Vergès-Belmin	
United States of America	275
Laboratory Study on Desalination by Poultices T. Lombardo, S. Simon	
Latvia	287
Desalination of Stone Objects in Latvia L. Krage, I. Vitina, S. Igaune, I. Sidraba	
Russia	295
Case Study: Salt Damage and Desalination of Limestone in George Cathedral of Yuriev-Polskoy and the Portal of Archangelsk Cathedral in Moscow Kremlin E. Antonova, O. Postnikova, A. Zacharova	
Germany	301
The Treatment of Salt Effected Wall Paintings as Interdisciplinary Task, Seen from the View of a Conservator H. Leitner	
Netherlands	315
Transport and Crystallisation of Salts in Porous Materials R.P.J. van Hees, B. Lubelli	

Spain	329
New Developments for Preventing Salt Damage to Porous Ornamental Materials through the Use of Crystallization Inhibitors C. Rodriguez-Navarro, L.L. Fernandez, E. Sebastian	
United States of America	341
The Salt-laden Rock-carved Tomb Façades in Petra, Jordan: Scientific Investigations S. Simon, M. Shaer, E. Kaiser	
Austria	351
Investigations on Salt-loaded Wall Paintings in the Area of Conflict between Natural Sciences, Restoration and the Need for Information of the Decision Makers as Well as the Public by the Example of St. Georgen ob Judenburg (Steiermark/Styria) J. Weber	
List of authors	
Short CV's	