

CONTENTS

Part I

Structural Failure and Reflective Practice <i>D. I. Blockley</i>	1
The Best Structural Engineering Laboratory in the World <i>N. FitzSimons</i>	19
Lessons to be Learned From Fatigue Damage Accidents of Steel Bridges <i>Ch. Miki</i>	21
Utilization of Information Concerning the Character and Reasons of the Buildings Defects and Failures - a TZÚS Approach <i>V. Beranová</i>	33
Advanced Computer Technology Helps Reducing the Failure Risk <i>M. Guštar, P. Marek, P. J. Tikalsky</i>	39

Part II

The Survey and the Rehabilitation Project for the Rolling Track of a 380/80 - Ton Overhead Travelling Crane <i>N. Baluț, A. Moldovan</i>	49
Failures of Load-Bearing Structures of Lažanský Palace in Prague <i>E. Burgetová</i>	55
Notes on Failures of Stone Elements <i>M. Drdáccký</i>	59
Failures of Transport Pipelines Under Pulsating Load <i>L. Gajdoš, J. Jíra, M. Micka, J. Němec</i>	67
On Two Working Accidents During Water Supply Constructions <i>J. Kratěna</i>	75
Failures of External Ceramic Tiling <i>J. Krňanský, I. Holub</i>	79
Sway Control of Unsymmetrical Load - Bearing Systems <i>O. Löwitová, M. Tocháček</i>	85
Construction Failures of Buildings on Clays <i>V. Maceková</i>	91

Failure of Historical Building in Connection with Reconstruction of Neighbouring Building <i>L. Mikš</i>	103
The Verification of the Statical Function of the Stiffening System at the Reconstructions of the Sacral Buildings <i>M. Pavlík</i>	109
Failures vs. Safety of Operation R. C. Silos Cement <i>L. Runkiewicz, J. W. Zieliński</i>	115
Failures Caused by Humid and Aggressive Medium <i>B. Straka, L. Matějka</i>	121
General Classification of Construction Damages Regarding with Dynamic Characteristics of the Rock Environment <i>B. Svoboda</i>	129
Defects in the Roof of the Former Com-Party District Committee and in a Cattle-Shed <i>M. Tocháček, O. Löwitová</i>	141
Examples of Rehabilitation of Collapsed Structures <i>T. Vaněk</i>	145
Collapse of Masonry Structures <i>T. Vaněk</i>	151
Lessons From Load Tests of Old Prestressed Concrete Bridges <i>B. Voves</i>	157
Investigation of Geotechnical Engineering Failures <i>J. S. Ward</i>	161
Damages of Rail Strips in the Prague Underground Railway <i>V. Weiss</i>	165
Failure of XI Storeys Prefabricated Apartment Building Due to Gas Explosion in the Basement <i>J. W. Zieliński</i>	171